



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car
(Co. Reg. No
Blk 3022A Ubi Road 1 #01-4
T: +65 6741 5336 | F:
E: claims@pro
W: www.pro

TP INSURER: India International Insurance Pte Ltd (HQ)
NA
Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0721-6447
Policy No:		Date of Loss:	25/07/2021
Vehicle Reg. No.:	SLB7565M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM MARGUERITE CARLA PHIPPS		
Make/Model:	NISSAN NOTE, 1.2 (A)	Vehicle Reg. Date:	21/04/2016
Vehicle Colour:	RED		
Engine No:	HR12172788B	Chassis No:	JN1TB AE12Z0982393
Odometer:	84698 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO THE ATTACH		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	13,780.50
Labour	601.00
Paintwork Labour	3,630.00
Towing	1,200.00
	0.00
Gross Total (\$\$)	19,211.50
+ GST 7.00% (\$\$)	1,344.81
Nett Amount (\$\$)	20,556.31

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jul 2021)
 Parts: 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/SLB7565M/28/07/2021 12:30
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER / DE	0.00	0.00	*494.30 F
2	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH - CA	0.00	0.00	*55.00 F
3	10	NA	*FRONT BUMPER CLIPS / MC	0.00	0.00	*44.00 F
4	1	NA	*FRONT BUMPER FOG LAMP - LH ?	0	0.00	*321.60 FS
5	1	NA	*FRONT BUMPER FOG LAMP - RH ?	0	0.00	*321.60 FS
6	1	NA	*FRONT BUMPER REINFORCEMENT ? BT	0.00	0.00	*419.70 F
7	1	NA	*FRONT BUMPER FOAM / CAA	0.00	0.00	*240.90 F
8	1	NA	*FRONT BUMPER TOP COVER / BR	0.00	0.00	*27.00 F
9	5	NA	*FRONT BUMPER TOP COVER CLIPS / MC	0.00	0.00	*22.00 F
10	1	NA	*FRONT BUMPER UNDER COVER / CAA	0.00	0.00	*378.40 F
11	10	NA	*FRONT BUMPER UNDER COVER CLIPS / MC	0.00	0.00	*44.00 F
12	1	NA	*FRONT BONNET / BT	0.00	0.00	*847.80 F
13	1	NA	*FRONT BONNET HINGE - LH / BT	0.00	0.00	*42.00 F
14	1	NA	*FRONT BONNET HINGE - RH X	0.00	0.00	*42.00 F
15	1	NA	*FRONT BONNET INSULATOR X	0.00	0.00	*89.70 F
16	4	NA	*FRONT BONNET LOCK X	0.00	0.00	*317.60 F
17	1	NA	*LOGO X	0.00	0.00	*64.90 F
18	1	NA	*FRONT BONNET CABLE X	0	0.00	*39.60 FS
19	1	NA	*FRONT FENDER - LH / MC	0.00	0.00	*544.40 F
20	1	NA	*FRONT FENDER COWLING - LH / TN	0.00	0.00	*100.50 F
21	10	NA	*FRONT FENDER COWLING CLIPS - LH / MC	0.00	0.00	*44.00 F
22	1	NA	*FRONT WHEELHOUSE PANEL - LH / CAA	0.00	0.00	*431.60 F
23	1	NA	*FRONT GRILLE ASSY W/NISSAN LOGO / CAA	0.00	0.00	*276.70 F
24	1	NA	*FRONT SUPPORT PANEL ASSY (TOP) / CAA	0.00	0.00	*323.20 F
25	1	NA	*FRONT SUPPORT PANEL TOP GARNISH / CAA	0.00	0.00	*276.70 F
26	10	NA	*FRONT SUPPORT PANEL TOP GARNISH CLIPS / MC	0.00	0.00	*44.00 F
27	2	NA	*FRONT HEADLAMP ASSY / CAA	0.00	0.00	*3,229.20 F
28	1	NA	*AIRCON CONDENSER ?	0	0.00	*696.90 FS
29	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH = SDR	0	0.00	*38.40 FS
30	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH	0	0.00	*38.40 FS
31	1	NA	*FUSE BOX (UPPER) / SDR	0.00	0.00	*48.30 F
32	1	NA	*FUSE BOX (MIDDLE) / SDR	0.00	0.00	*48.30 F
33	1	NA	*FUSE BOX (LOWER) / SDR	0.00	0.00	*39.80 F
34	1	NA	*FRONT RIM - LH / CAA	0.00	0.00	*748.00 F
35	1	NA	*FRONT LOWER ARM - LH	0.00	0.00	*195.50 F
36	1	NA	*FRONT KNUCKLE - LH	0	0.00	*382.50 FS
37	1	NA	*FRONT KNUCKLE BEARING - LH / SDR	0	0.00	*134.60 FS
38	1	NA	*FRONT WHEEL HUB - LH	0	0.00	*221.10 FS
39	1	NA	*FRONT ABSORBER - LH	0	0.00	*294.30 FS
40	1	NA	*FRONT ABSORBER TOP MOUNTING - LH	0.00	0.00	*90.60 F
41	1	NA	*STEERING RACK / SDR	0	0.00	*1,470.80 FS
42	1	NA	*CROSSMEMBER	0	0.00	*323.60 FS
43	1	NA	*RADIATOR ?	0	0.00	*584.00 FS
44	1	NA	*RADIATOR TOP HOSE ?	0	0.00	*36.10 FS
45	1	NA	*RADIATOR LOWER HOSE ?	0	0.00	*54.90 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

13,780.50

Progressive Car Care Pte Ltd/SLB7565M/28/07/2021 12:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BATTERY	200.00
2	1	FRONT NUMBER PLATE WITH CASING	50.00
3	1	FRONT TYRE - LH	280.00
4	1	QUARTER GLASS SEALANT	10.00
5	1	TO REFILL RADIATOR COOLANT	50.00
6	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			601.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON FRONT HEAD; LH FRONT DOOR; SUPPORT PANEL & WHEELHOUSE PANEL; DOOR PILLAR	New	1,200.00
Labour Items			
2	TO KNOCK OUT DENTS; STRAIGHTEN FRONT CHASSIS; CUT/WELD SUPPORT PANEL; LH FRONT WHEEL HOUSE; REMOVE; REPLACE ACCIDENT PARTS	New	1,600.00
3	TO REMOVE; REFIX FENDER QUARTER GLASS	New	80.00
4	TO REMOVE; REPLACE CROSSMEMBER; STEERING RACK	New	500.00
5	TO 4 WHEEL ALIGNMENT	New	100.00
6	TO REMOVE; REPLACE RIM & REBALANCING	New	50.00
7	TO CHECK WIRING; SOCKETS INCLUDING FOCUS OF HEADLAMP	New	50.00
8	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
9	TO RESET CHECK LIGHT	New	200.00
10	TO TUFF-KOTE	New	120.00
11	TO REMOVE; REPLACE FUSE BOX TOP; LOWER; CENTRE; TRANSFER FUSE AND RELATED PARTS	New	180.00
12	TO REMOVE; REPLACE FRONT CROSSMEMBER; LH FRONT UNDERCARRIAGE	New	650.00
Gross Labour Cost (\$\$)			4,830.00

Progressive Car Care Pte Ltd/SLB7565M/28/07/2021 12:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

8 Days.
part by part.
before paint photos.
Eric Qian
8288 0282
29/7/21

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: