



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 29.07.2021
Emailed : 19.08.2021, 11.10am
Date Survey : 30.07.2021

VEHICLE NO : SMR 4117 Y
MODEL : KIA CERATO 1.6 A EX
WIP : 37006

Material	:	\$	<u>5,900.60</u>
Labour	:	\$	<u>4,860.00</u>
Sub-Total	:	\$	<u>10,760.60</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>10,760.60</u>
GST 7%	:	\$	<u>753.24</u>
Grand Total	:	\$	<u>11,513.84</u>
Finalise By/Date	:		<u>LOI / 18/08/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 30/07/2021	Cust No/Name	/NG XUE LI, SHERLENE (HUANG XUEL
	Reg No/Reg Date	SMR4117Y / 03/01/2020
	Date In/Mileage	30/07/2021/ 48709
	Chassis/Package	KNAF3416ML5059975 /#
	Engine No	G4FGKH739336
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/08/2021/ 12:10	BLE	260 / AiTing	37006			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR END PANEL, BOOT LID, BOOT LID SPOILER, REPAIR REAR FLOOR PANEL, LH REAR FENDER, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2080.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR END PANEL, BOOT LID, BOOT LID SPOILER, LH REAR FENDER, RH REAR FENDER, REAR FLOOR PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2100.00
E PNT88000 REMOVE & REINSTALL BOOT LID COMPONENTS TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & REINSTALL REAR FLOOR BOARD, CARPETS & TRIM TO FACILITATE REPAIR								✓ 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M SUNDRY SUPPLY BODY PANEL SEALANT								✓ 60.00
M SUNDRY SUPPLY C&C BADGE								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE REAR LICENSE PLATE WITH PLASTIC FRAME								✓ 50.00
X				K3 BOOT LIP SPOILER	1.00	✓ 211.00	00.00	211.00
X				PANEL ASSY-TRUNK LID	1.00	✓ 1297.00	20.00	1037.60
X				HINGE ASSY-TRUNK LID,LH	1.00	✓ 97.00	20.00	77.60

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 30/07/2021	Cust No/Name	/NG XUE LI, SHERLENE (HUANG XUEL
	Reg No/Reg Date	SMR4117Y / 03/01/2020
	Date In/Mileage	30/07/2021/ 48709
	Chassis/Package	KNAF3416ML5059975 /#
	Engine No	G4FGKH739336
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	18/08/2021/ 12:10	BLE	260 / AiTing	37006		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	HINGE ASSY-TRUNK LID,RH			1.00	✓ 97.00	20.00	77.60
X	W/STRIP-TRUNK LID OPNG			1.00	✓ 100.00	20.00	80.00
X	TRIM ASSY-TRUNK LID			1.00	✓ 202.00	20.00	161.60
X	LATCH ASSY-TRUNK LID			1.00	✓ 112.00	20.00	89.60
X	LOGO ASSY-KIA SUB			1.00	✓ 32.00	20.00	25.60
X	EMBLEM-CERATO			1.00	✓ 28.00	20.00	22.40
X	LAMP ASSY-CENTER GARNISH			1.00	✓ 690.00	20.00	552.00
X	LAMP ASSY-REAR COMB INSIDE,LH			1.00	✓ 608.00	20.00	486.40
X	LAMP ASSY-REAR COMB INSIDE,RH			1.00	✓ 608.00	20.00	486.40
X	LAMP ASSY-REAR COMB OUTSIDE,LH			1.00	✓ 675.00	20.00	540.00
X	LAMP ASSY-REAR COMB OUTSIDE,RH			1.00	✓ 675.00	20.00	540.00
X	PANEL ASSY-BACK			1.00	✓ 324.00	20.00	259.20
X	TRIM ASSY-RR TRANSVERSE			1.00	✓ 41.00	20.00	32.80
X	COVER-RR BUMPER			1.00	✓ 651.00	20.00	520.80
X	COVER-RR BUMPER LWR			1.00	✓ 241.00	20.00	192.80
X	COVER-RR BUMPER FOG LAMP,RH			1.00	✓ 19.00	20.00	15.20
X	EXTN WIRING ASSY-BWS			1.00	✓ 207.00	20.00	165.60
X	BEAM-RR BUMPER			1.00	✓ 318.00	20.00	254.40
X	STAY-RR BUMPER RH			1.00	✓ 65.00	20.00	52.00
X	FASTENER			5.00	1.00	20.00	4.00
X	CLIP			10.00	2.00	20.00	16.00
Z	TEXT						
	AIG OD CLAIM. (WITH INJURY CLAIM)						
	DOA: 29.07.21						
	SURVEYOR STEVE LKK 30.07.21						
	POLICY NO : 2000000418 REPAIR 08 DAYS						
Guarantee Your Warranty, Maintain with Cycle & Carriage!							

Parts	5,900.60	Nett	10,760.60
Labour	4,650.00	7% GST on	10760.60
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	11,513.84
Diagnostics Job	0.00		
Sundry/Others	160.00		
Total(w/o GST)	10,760.60		



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMR 4117 Y

<u>Materials</u>		<u>Cost (\$)</u>
1	Fastener (x5)	5.00 ✓ nec
2	Clips (x10)	20.00 ✓ nec
Total		25.00
Less 20% discount		5.00
Total after discount		20.00
7% GST		1.40
Grand total		<u>21.40</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240



CERATO/FORTE../2020/G 1.6 MPI..

VCI




Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0251

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0192

OS Ver.

Android 10