

Not Authorized
Painting B4 paint

87370.53

AAD2107- 119.

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHB7724T

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

02 AUG 2021

SHB7724T
JTDKB3FU303081296
TOYOTA
PRIUS
29/07/2021
ERAO.
18/06/2019

		PART	LIST	
1	COVER, REAR BUMPER		\$	Bu 442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER		\$	B1 332.70 ✓
1	GUARD, REAR BUMPER, CENTER		\$	B1 576.30 ✓
1	SEAL, REAR BUMPER SIDE, LH		\$	Ln 88.50 X
1	RETAINER, REAR BUMPER SIDE, LH		\$	Ln 116.50 X
1	PANEL SUB-ASSY, BODY LOWER BACK		\$	B1 650.30 ✓
1	FILLER, REAR BUMPER EXTENSION, LH		\$	h 123.70 X
1	FILLER, REAR BUMPER EXTENSION, RH		\$	h 123.70 X
1	LENS AND BODY, REAR LAMP, LH		\$	CM 502.00 ✓
1	LENS & BODY, REAR COMBINATION LAMP, LH		\$	Ln 443.30 X
1	LENS AND BODY, REAR LAMP, RH		\$	Ln 502.00 X
1	LENS & BODY, REAR COMBINATION LAMP, RH		\$	Ln 451.80 X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH		\$	Ln 54.40 X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH		\$	Ln 54.40 X
1	PANEL SUB-ASSY, BACK DOOR		\$	B1 1,147.80 ✓
1	STAY ASSY, BACK DOOR, LH		\$	Ln 242.50 X
1	STAY ASSY, BACK DOOR, RH		\$	Ln 242.50 X
1	HINGE ASSY, BACK DOOR, LH		\$	Dis 61.00 ✓
1	HINGE ASSY, BACK DOOR, RH		\$	Dis 61.00 ✓
1	SPOILER SUB-ASSY, REAR		\$	CM 1,575.40 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE		\$	Wap 925.60 ✓
1	ORNAMENT SUB-ASSY, BACK DOOR		\$	Ln 47.90 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2		\$	Ln 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1		\$	Ln 54.60 ✓
1	COVER, REAR FLOOR (CTR)		\$	Ln 229.90 X
1	COVER, FLOOR UNDER, NO.2 (RH)		\$	Ln 241.90 X
1	COVER, FLOOR UNDER, NO.1 (LH)		\$	Ln 175.10 X
TOTAL			\$	9,522.00
25%			\$	2,380.50
			\$	7,141.50

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHB7724T

AAD2107-

1SET REAR NUMBER PLATE WITH HOLDER	\$	Sm	120.00	X
1 REAR BUMPER SIDE CLIP	\$	nn	60.00	X
1 BOOTLID STICKER 'TRANSCAB'	\$	nn	100.00	305N
1 BOOTLID STICKER '65553333'	\$	nn	100.00	305N
1SET PARKING AID	\$	nn	700.00	2205N
1SET REAR BUMPER CLIP	\$	nn	85.00	505N
1 REAR BUMPER PROTECTOR	\$	NTP	180.00	X
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00	X
2SET TAILLAMP CLIP	\$	nn	100.00	X
TOTAL	\$		1,520.00	
TOTAL PARTS	\$		8,661.50	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	500-600f
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	Repair	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	8801
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
TOTAL	\$		5,100.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7724T

AAD2107-119

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB7724T

JTDKB3FU303081296

TOYOTA

PRIUS

29/7/2021

ERGO

18/6/2019

SUPPLEMENTARY ESTIMATE

LIST

- 1 ANTENNA, ELECTRICAL KEY
1 MOULDING SUB-ASSY, ROOF TOP

\$ *m* 72.00 ✓
\$ *my Bro* 656.90 ✓

TOTAL	\$	728.90
25%	\$	182.23
	\$	546.68