

Not Authorized
 Anthony Bepem
 9 days
 1/12/21 @ 7350hr



Tan Cher Hui Philip
 11 Yio Chu Kang Drive Atelier Villas
 Singapore 786284

File No : SH/2021/070/07/010/TP
 Date : 30-July-2021

Estimated cost of repair for vehicle no : SME1830J Mitsubishi Lancer
 Accident involving vehicle no: SME1830J & SJG8809B on 30.07.2021

Description	Quantity	Cost Price
Tailgate	1	\$ 970.00 ✓
Tailgate centre moulding	1	\$ 466.00 ✓
Tailgate centre moulding emblem	1	\$ 39.00 ✓
Tailgate badge "outlander"	1	\$ 86.00 ✓
Tailgate badge "mivec technology"	1	\$ 75.00 ✓
Tailgate badge "C&C"	1	\$ 65.00 ✓
Tailgate weatherstrip	1	\$ 192.00 ✓
Tailgate inner trim board 302	1	\$ 360.00 ✓
Tailgate inner trim board clips (1 set)	1	\$ 28.00 ✓
Tailgate inner lock	1	\$ 428.00 ✓
RH Tailgate inner tail lamp	1	\$ 397.00 ✓
LH Tailgate inner tail lamp	1	\$ 397.00 ✓
RH outer tail lamp	1	\$ 563.00 ✓
LH outer tail lamp	1	\$ 563.00 ✓
Rear windscreen moulding	1	\$ 160.00 ✓
Rear bumper 873	1	\$ 873.00 ✓
Rear bumper clips (1 set)	1	\$ 38.00 ✓
Rear bumper centre lower moulding	1	\$ 209.00 ✓
RH Rear bumper retainer	1	\$ 24.00 ✓
LH Rear bumper retainer	1	\$ 24.00 ✓
RH Rear bumper bracket	1	\$ 71.00 ✓
LH Rear bumper bracket	1	\$ 71.00 ✓
RH rear bumper fog lamp	1	\$ 120.00 X
LH rear bumper fog lamp	1	\$ 120.00 X
Rear end panel	1	\$ 299.00 ✓
RH rear end corner panel	1	\$ 188.00 X
LH rear end corner panel	1	\$ 188.00 X
Rear end panel top trim	1	\$ 111.00 ✓
Rear floor panel	1	\$ 743.00 X
Rear floor top board	1	\$ 266.00 ✓
Rear exhaust muffler	1	\$ 548.00 ✓
Rear bumper side garnish LH 980.00 ✓ not		\$ 8,682.00
Less 10%		\$ 868.20
Tailgate open & close switch 156.00 ✓		\$ 7,813.80

Rear windscreen sealant	1	S. Nett	\$	80.00	405m
Rear windscreen inner rubber seal	1	S. Nett	\$	28.00	✓
Rear parking sensors (1 set)	1	S. Nett	\$	280.00	200g
Rear parking camera	1	S. Nett	\$	380.00	✓
Rear bumper side lower spoiler set	1	S. Nett	\$	636.00	✓

To remove and reinstall rear windscreen and conduct water leak test \$ 120.00 ✓

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, RH rear fender, LH rear fender, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment \$ 1,100.00 900l

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality \$ 35.00 20l

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material \$ 1,200.00 1000l

To apply anti-corrosion Tuff-Kote \$ 100.00 60l

Acc. by car for floor run

120 → 80 ✓ \$ 11,772.80

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: