

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III21006746/Btf3-1 Date: 30/07/2021 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 9277Z	Veh. Inspected	SJH 9273J	
Policy No.	D20MFL0007747	Coverage (\$)	0.00	
Claim No.	MFL2021D0002580	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	30/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/06/2021	Inspection Date	30/07/2021	
Survey held at	14 ang mo kio st 63 block B			
Repairer	ASSURE AUTO ASSIST PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				