

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
Mr Abdul Rahman Bin Jafar	Cust No/Name	/Mr Abdul Rahman Bin Jafar		
THE TRANSPORT OF THE CAPTURE	Reg No/Reg Date	SLX7241G / 09/04/201		
Blk 679 Choa Chu Kang Crescent #07-586 Singapore 680679	Date In/Mileage	/ 0		
	Chassis No	KNAFZ411MJ5762759		
	Engine No	G4FGHH692842		
Contact No Mobile: 81251842	Make/Model	KIA/CERATO K3 1.6 A SX SR		
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00081	Cash	28/07/2021/ 11:58		282 / Kevin Leon	g	36912		
		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	DEAD DIE	DED DODYKIT A AFFEC	FED ACEA					1920.00
E PNT98000	REAR BUM	PER, BODYKIT & AFFEC	IED AREA					1650.00
	RK ON RE	AR BUMPER & BODYKIT						1050.00
E PNT88000								150.00
	INSTALL	REAR PARKING ASSIST						50.00
M SUNDRY TO APPLY	SFALANT	ON AFFECTED AREA						50.00
M SUNDRY	JEALANT	ON ATTECTED AREA						50.00
	RUST PRE							
A 54900099	DINC 0 C	HASSIS ELECTRICAL SY	Д!		Л _			120.00
A 10028901	KING & C	HASSIS ELECTRICAL SY	45/1	110019	17/0)		280.00
TO CARRY	OUT DIA	GNOSTIC CHECK ON ELEC	TRONIC COL	NTROL SYSTEM	11410	7		200.00
M SUNDRY								50.00
SUNDRIES M NEW K3 B					1.00	1177.00	00 00	1177.00
M COVER-RR					1.00		00.00	688.00
	BUMPER,	CTR			1.00		00.00	315.00
M BEAM-RR		OTI			1.00		00.00	318.00
M BRACKET-		I WR MTG			2.00		00.00	10.00
M BRACKET-					1.00		00.00	5.00
			181					
Confirm &	accepted	by						
						Ne	tt	6,783.0
					7% GST on			474.8
					т	otal Payab	10	7,257.8
						otal rayab	16	7,257.0
Authorized	signator	y and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.