



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Abdul Rahman Bin Jafar	Cust No/Name /Mr Abdul Rahman Bin Jafar
Blk 679 Choa Chu Kang Crescent	Reg No/Reg Date SLX7241G / 09/04/201
#07-586	Date In/Mileage 22/09/2021/ 0
Singapore 680679	Chassis No KNAFZ411MJ5762759
Contact No Mobile: 81251842	Engine No G4FGHH692842
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	22/09/2021/ 10:35	TLK	282 / Kevin Leong	36912		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 1 <sup>80</sup>						1040	1920.00
REPLACE REAR BUMPER, BODYKIT & AFFECTED AREA							
REPAIR ON BOOT LID 1/2							1650.00
E PNT98000							150.00
PAINT WORK ON REAR BUMPER, BOOT LID & BODYKIT							
E PNT88000							50.00
REMOVE & INSTALL REAR PARKING ASSIST							
M SUNDRY							50.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							50.00
PERFORM RUST PREVENTION							120.00
A 54900099							280.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							50.00
SUNDRIES							
M SUNDRY							
TO SUPPLY C & C EMBLEM							
M NEW K3 BODYKIT X R				1.00	1177.00	00.00	1177.00
M COVER-RR BUMPER				1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR				1.00	315.00	00.00	315.00
M BEAM-RR BUMPER				1.00	318.00	00.00	318.00
M BRACKET-RR BEAM LWR MTG				2.00	5.00	00.00	10.00
M BRACKET-RR BEAM LWR,CTR				1.00	5.00	00.00	5.00
M LOGO ASSY-KIA SUB				1.00	37.00	00.00	37.00
M EMBLEM-CERATO				1.00	35.00	00.00	35.00

Estimate

Steve CLKK)  
22/9/21, 11.00am

WHL RL  
4 dgs  
PIP

# Estimate

Steve (CLKK)  
 22/9/21, 11.00am

WRL RL  
 4 dys  
 P/P

Confirm & accepted by  
 the Reparer of the following:

- To resurvey before/after spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- The above estimate is valid for 14 days

Authorized signatory and company stamp

By Bel Sy  
 Nett 6,905.00  
 7% GST on 6905.00 483.35  
**Total Payable 7,388.35**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.