

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0600/2021/GW
DATE : 24-Jul-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/7/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

17-Sep-21

OWNER'S NAME : MR ANG YUAN PIN(HONG YUANBIN)
ADDRESS : BLK 122 C SENG KANG EAST WAY
#04-29
SINGAPORE 53122
TELEPHONE : HP +65 96953801
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100479292-04
VEHICLE NO : **SLE 6941 B**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 7/28/2016
ENGINE NO : CVC 556146
CHASSIS NO : WAUZZZ8V7G1099550
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jul-21
PLACE OF ACCIDENT : LEVEL 3, 121 E MULTI STOREY CAR PARK
(MSCP) SENG KANG EAST WAY

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 6941 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(Added \$150.00 for repair LHS rear fender)</i>	\$	1,400.00	\$ 650.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$	2,000.00	\$ 1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,872.00	\$ 2,222.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 6941 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,070.00	\$	1,656.00
2	REAR BUMPER FIXING PARTS	1	\$ 193.00		
3	REAR BUMPER GUIDE SECTION LH RH	2	\$ 32.00		
4	REAR LIGHT REFLECTOR LH	1	\$ 41.00		
5	LED TAIL LIGHT LH	1	\$ 877.00		
6	REAR BUMPER GUIDE SECTION LH UPPER	1	\$ 67.00	\$	52.96
7	SUNDRIES		\$ 200.00		
TOTAL SPARE PARTS		:	\$ 3,480.00	\$	1,708.96
TOTAL LABOUR CHARGES		:	\$ 3,872.00	\$	2,222.00
GRAND TOTAL		:	\$ 7,352.00	\$	3,930.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-02/09/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT