

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569644
Tel: 6452 4898 Fax: 6452 4868
Email: sg_motor_enterprise@yahoo.com.sg

Date: 26 April 2021
To : LKK

By Fax: 6256-4315

Attn : Bryan
Tel : 97237799

VEHICLE NO : VCT 3242
ACCIDENT DATE: 27 March 2021

Yamaha LV 135

Description	Qty	Quotation \$
1 Handle Bar Hw	1	95.00 X
2 Handle Bar Bracket Hw	1	120.00 X
3 LH Inner Panel CRMC	1	120.00 ✓
4 Front LH Panel - Fairing CRMC	1	150.00 ✓ 140.00
5 Front RH Panel - Fairing CRMC	1	160.00 ✓ 140.00
6 Sprocket Chain Guard Down CRMC	1	180.00 ✓
7 Balancer Hw	1 set	80.00 X
	Sub-Total	580.00
	Less 10%	522.00
	Sub-Total	905.00
		90.50
		814.50

Nett items

1 Body sticker - 1 set Hw		90.00 60/-
2 Repress rear rim Hw	160.00	110.00 X
3 Labour charge to remove & replace parts		120.00 100/-
	Sub-Total	320.00
	Nett Total	1,134.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you.

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: