

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0612/2021/GW
DATE : 28-Jul-21
WIP : 37192

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/7/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHEN CHIN MIN
ADDRESS : 158, WATTEEN ESTATE
SINGAPORE 287609
TELEPHONE : HP +65 96666113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070017408
VEHICLE NO : **SMS 3016 C**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 20/2/2020
ENGINE NO : CVK 087199
CHASSIS NO : WAUZZZF4XKA113735
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jul-21
PLACE OF ACCIDENT : CTE TURN OFF TO YIO CHU KANG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 3016 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	Q /
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	Q ?
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	500 \$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET.	550 \$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 5,472.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 3016 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>re</i>	1	\$ 1,787.00	
2	FRONT BUMPER FIXING PARTS ?	1	\$ 587.00	
3	FRONT BUMPER SECURING STRIP ?	2	\$ 71.00	
4	FRONT BUMPER GRILLE-CENTER <i>NR</i>	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE ?	1	\$ 210.00	
6	RADIATOR GRILLE <i>Cut</i>	1	\$ 1,332.00	
7	FRONT AIR GUIDE GRILLE LH RH ?	2	\$ 270.00	
8	FRONT FOAM FILLER PIECE ?	1	\$ 124.00	
9	FRONT REINFORCEMENT BEAM ?	1	\$ 845.00	
10	FRONT BUMPER COVER ?	1	\$ 127.00	
11	" SIGN CAUTION " STICKER ?	1	\$ 14.00	
12	" AIR CONDITIONER " STICKER ?	1	\$ 8.00	
13	FRONT LOCK CARRIER BRACKET ?	1	\$ 137.00	
14	FRONT LOCK CARRIER SUPPORT LH RH ?	2	\$ 58.00	
15	FRONT SENSOR INNER / OUTER ?	2	TBC	
16	FRONT SENSOR SEAL RING ?	4	\$ 14.00	
17	FRONT HORN LH RH ?	2	\$ 252.00	
18	FRONT HORN BRACKET LH RH ?	2	\$ 58.00	
19	BONNET <i>X repair</i>	1	\$ 3,246.00	
20	BONNET ATTACHEMENT PARTS <i>X NN</i>	1	\$ 412.00	
SUB TOTAL SPARE PARTS		:	\$ 9,748.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 3016 G

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET IMPACT PROTECTION CENTER X	1	\$ 28.00	
22	BONNET IMPACT PROTECTION LH RH X	1	\$ 56.00	
23	BONNETBOWDEN RELEASE CABLE X	1	\$ 58.00	
24	BONNET BOWDEN CABLE CENTER X	1	\$ 58.00	
25	BONNET RELEASE CABLE COVER X	1	\$ 10.00	
26	BONNET RELEASE LEVER X	1	\$ 14.00	
27	BONNET STRIKER LH RH X	2	\$ 100.00	
28	BONNET LID LOCK X	2	\$ 427.00	
29	LED HEADLIGHT LH RH ?	2	\$ 15,386.00	
30	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM LH RH ?	2	\$ 420.00	
31	CORRUGATED PIPE FOR WASHER SYSTEM ?	1	\$ 93.00	
32	RADIATOR AIR GUIDE LH RH ?	2	\$ 56.00	
33	RADIATOR AIR GUIDE LH RH INNER ?	2	\$ 24.00	
34	RADIATOR AIR GUIDE UPPER ?	1	\$ 16.00	
35	RADIATOR AIR GUIDE LOWER ?	1	\$ 22.00	
36	FRONT NO. PLATE / 6T	S/N	\$ 60.00	
37	SUNDRIES ?		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 26,926.00	
TOTAL LABOUR CHARGES		:	\$ 5,472.00	
GRAND TOTAL		:	\$ 32,398.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

En. Aiamf.

20/7/21

Not Authorised.
before paint photos.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

Excess = TBA

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

3 Days

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: