

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/EP12/008111/493

ASSIGNMENT

From: Date:
Estimated Cost:
OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: FB4 54874
at Workshop m/s: Ench.
of: SKR8234P

Insured:
Policy No.
Claims No. DM21HO01109/MT
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$9500
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 131 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: LTA 83126 Vehicle: IN / OUT

Veh No: FBQ5487H Yr Regn: 23/10/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or GTR L50

Make: Honda Supra c.c. 149
Colour: Red/Black A/C: Insured / Std / NI / NA
Sp. Reading: 34993 T/Radio: Insured / Std / NI / NA
Eng/No:

C/No: MH1KB2119KK 088022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90 / 80 - 17
R: 120 / 70 - 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRC

Front 6 mm Rear 6 mm
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. 26/7/21 D.O.I. 2/8/21
Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear ~~20/5/21~~
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/8/21 L/S \$1400 confirmed with mr Leo. (Red \$4043.30, 74%)

16/8/21 Reconfirmed P/P \$60.00 and 1 day for repair
only rear portion confirmed with R. L. bike near fall on the floor
(Red \$5383.30, 99%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) 11/08 Typist

Date/Time, File Return to?

2)

Days Of Repair: 3 1

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 1400 P/P \$60)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

EQ

Name : SKK Works Pte Ltd

Accident Date : 26-Jul-21

Vehicle No : FBQ5487H

Vehicle Model : Honda Supra
GTR 150
Manual

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy <i>11</i>	\$ 680.00 <i>X</i>
1	Fork under bracket <i>11</i>	\$ 220.00 <i>X</i>
1	Front rim <i>11</i>	\$ 580.00 <i>X</i>
1	Front brake disc <i>11</i>	\$ 185.00 <i>X</i>
1	Front rim shaft <i>11</i>	\$ 50.00 <i>X</i>
1	Front rim bearing <i>11</i>	\$ 42.00 <i>X</i>
1	Handle bar <i>11</i>	\$ 88.00 <i>X</i>
1	Handle bar end <i>11</i>	\$ 32.00 <i>X</i>
1	Hand grip (1 set) <i>11</i>	\$ 76.00 <i>X</i>
1	Side mirror -R/H <i>cut n/c</i>	<i>68</i> \$ 120.00 <i>X</i>
1	Front signal lower garnish <i>ground n/c</i>	\$ 125.00 <i>X</i>
1	Brake lever <i>cut n/c</i>	<i>48</i> \$ 70.00 <i>X</i>
1	Fairing assy (1 set) <i>cut n/c</i>	\$ 625.00 <i>X</i>
1	Front footrest bracket <i>best n/c</i>	\$ 65.00 <i>X</i>
1	Front footrest rubber <i>7011 n/c</i>	<i>38</i> \$ 50.00 <i>X</i>
1	Brake pedal <i>BE n/c</i>	\$ 42.00 <i>X</i>
2	Rear footrest <i>11</i>	\$ 84.00 <i>X</i>
1	Rear footrest bracket <i>11</i>	\$ 78.00 <i>X</i>
1	Exhaust assy <i>2</i>	\$ 585.00 <i>X</i>
1	Exhaust protector <i>cut n/c</i>	\$ 105.00 <i>X</i>
1	Exhaust protector end cover <i>cut n/c</i>	\$ 85.00 <i>X</i>
		\$ 3,987.00
	Less 10%	\$ 398.70
		\$ 3,588.30

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : SKK Works Pte Ltd

Accident Date : 26-Jul-21

Vehicle No : FBQ5487H

Vehicle Model : Honda Supra
GTR 150
Manual

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>Rear Bmf</i>	\$	38.00	<i>10</i>
2	Fork oils <i>11</i>	\$	30.00	<i>X</i>
2	Fork oil seals <i>11</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set) <i>11</i>	\$	96.00	<i>X</i>
1	Sticker <i>11</i>	\$	95.00	<i>X</i>
1	Rear box <i>cut 11C</i>	\$	480.00	<i>250X</i>
1	Rear box bracket <i>Bmf 11C</i>	\$	180.00	<i>X</i>
		\$	975.00	

S/No. Labour

1	To check wiring and reset headlamp focusing	\$	11	80.00	<i>X</i>
2	To repair body frame	\$	11	380.00	<i>X</i>
3	To provide labour <i>and repair rear fender</i>	\$		420.00	<i>200</i>
		\$		880.00	

Grand Total

\$ 5,443.30

Singapore Dollars: Five Thousand Four Hundred Forty-Three and Cents: Thirty only

EROFIA MOTOR TRADING PTE LTD