

TP Chlm
Veron.

SMC8458R 2018 July.
Mitsubishi Attrage 1193
MMBSTA13AJH002500

Rear Bumper	Distorted	708	-
Rear Bumper Clips	new	30(SN)	-
Rear Bumper Side Holder Rtl.	Dist	26	-
Rear Bumper Lower Spoiler	torn	850(SN)	600(SN)
Taillamp RH.	wt	276.40	-
Taillamp Panel RH.	NP	245.40	X
Rear RH Fender.	Distorted	798	-
Rear RH Fender Inner Shield	torn	58.10	-
Rear RH Fender Inner Shield Clips	new	40(SN)	-
Rear RH Fender Inner Trim	NP	181.70	X
Rear RH Fender Inner Trim Clips	NP	30(SN)	X
Rear RH Door	Distorted	831.	-
Rear RH Door Lock	Damaged	186.40	-
Rear RH Door Weatherstripe	NP	168.80	X
Rear RH Door Inner Trim Board	crushed	495	-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4894.80

SMC8458R.

Rear RH Door Inner Trim Board Clips	Nel	30(SN) ✓
Rear RH Door Handle	Rys	148.60 X
Rear RH Door Glass Regulator Gear	Dunc	185.60 ✓
Rear RH Door Glass Regulator Motor	in	352 X
Rear RH Wheel Rim	AL m	800(SN) X
Rear Windscreen Moulding	?	105 ✓
Rear Windscreen Sealant.	Nel	60(SN) ✓
	S.N: 730	
	3669.50	
	330255	

Panel Bending
Spray Painting.
Wiring.

2140

1400	800
1400	900
50	30
100	50
150	60
150	100
180	120
150	80
150	X

tel. 61255

2/5: 49k

06 Days.

To remove cruise sensor
To remove upholstery.
To spray buff coat.
To remove rear windscreen
To transfer door fittings
To perform wheel alignment.

5411.20

10,306.00