

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Document no. 02-08-2021
Document date 5211043795
Customer no. 201009404M
Customer GST-ID 30001
Dealer 2021028790/ 1
Job order number 02-08-2021
Job order date PEARLYN CHEONG
Service Advisor

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TAN
KIAN SOON, JEREMY
(CHEN JIANSHUN)
BLK 316 TAMPINES ST 33
#06-178
SINGAPORE 520316

License plate	Model code	First registration	VIN	Model	Mileage
SMR8263G	BQ13HZC0	23-01-2020	WVWZZZAUZLW008049	Golf Comfortline 1.4 TSI 92kW DSG	21

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G6807417BQGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,303.20	#1	1,303.20	1,394.42
5G6807393	Guide Piece (LHR bumper bracket) <i>2B.New</i>	1	pcs.	40.52	#1	40.52	43.36
5G6807393A	Guide Piece (LHR Bumper retainer) <i>3? x m</i>	1	pcs.	40.52	#1	40.52	43.36
5G6807863C	Attachment Strip <i>x m</i>	1	pcs.	69.96	#1	69.96	74.86
5G0807305D	Bumper (reinforcement) <i>3? x m</i>	1	pcs.	650.77	#1	650.77	696.32
5G0945105C	Reflector <i>com</i>	1	pcs.	75.05	#1	75.05	80.30
5G0919491D	Sensor Bracket <i>new</i>	1	pcs.	12.71	#1	12.71	13.60
5G0919492D	Sensor Bracket <i>new</i>	1	pcs.	13.20	#1	13.20	14.12
5G0919491E	Sensor Bracket <i>new</i>	1	pcs.	12.71	#1	12.71	13.60
5G0919491D	Sensor Bracket <i>new</i>	1	pcs.	12.71	#1	12.71	13.60
5Q0919275B GRU	Sensor Primed <i>mis</i>	1	pcs.	178.20	#1	178.20	190.67
5Q0919133 9B9	Seal Ring Satin Black <i>3? x m</i>	1	pcs.	1.31	#1	1.31	1.40
D 822150A1	Bonding Agent For Plastic <i>new</i>	1	pcs.	65.18	#1	65.18	69.74
D 180KU2A1	2k-Plastic Adhesive <i>new</i>	1	pcs.	81.16	#1	81.16	86.84
5G0945095Q	Led Tail Light <i>com</i>	1	pcs.	591.48	#1	591.48	632.88
5G0853687 2ZZ	Inscription Bright Chrome (Golf) <i>new</i>	1	pcs.	80.16	#1	80.16	85.77
	LABOU R	4	pcs.	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1 <i>2400</i>	3,200.00	3,424.00

Quotation valid till 09-08-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,788.84	7%	738.42	10,548.84	11,287.26
Total	760.00	9,788.84		738.42	10,548.84	11,287.26

* paint Rear bumper, LHR fender & rear boot .

* Repair LHR fender dent

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

1 Alexandra Road
Singapore 159934
Biz. Reg No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TAN
KIAN SOON, JEREMY
(CHEN JIANSHUN)
BLK 316 TAMPINES ST 33
#06-178
SINGAPORE 520316

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

02-08-2021
5211043795
201009404M
30001
2021028790/ 1
02-08-2021
PEARLYN CHEONG

License plate SMR8263G	Model code BQ13HZC0	First registration 23-01-2020	VIN WVWZZZAUZLW008049	Model Golf Comfortline 1.4 TSI 92kW DSG	Mileage 21
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions). —

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul

Hp 90012068

5 days

03/08/21 @ 0900

Resurvey before paint