

VOLKSWAGEN CENTRE SINGAPORE

517 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TAN
KIAN SOON, JEREMY
(CHEN JIANSHUN)
BLK 316 TAMPINES ST 33
#06-178
SINGAPORE 520316

Document no.
Document date 02-08-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021028790/ 1
Job order date 02-08-2021
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SMR8263G	BQ13HZC0	23-01-2020	WWWZZZAUZLW008049	Golf Comfortline 1.4 I TSI 92kW DSG	21

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G6807417BQGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,303.20	#1	1,303.20	1,394.42
5G6807393	Guide Piece	1	pcs.	40.52	#1	40.52	43.36
	(LHR bumper bracket) <i>de</i>						
5G6807393A	Guide Piece	1	pcs.	40.52	#1	40.52	43.36
	(LHR Bumper retainer) <i>??</i>						
5G6807863C	Attachment Strip <i>X</i>	1	pcs.	69.96	#1	69.96	74.86
5G0807305D	Bumper	1	pcs.	650.77	#1	650.77	696.32
	(reinforcement) <i>??</i>						
5G0945105C	Reflector <i>cm</i>	1	pcs.	75.05	#1	75.05	80.30
5G0919491D	Sensor Bracket <i>cm</i>	1	pcs.	12.71	#1	12.71	13.60
5G0919492D	Sensor Bracket <i>cm</i>	1	pcs.	13.20	#1	13.20	14.12
5G0919491E	Sensor Bracket <i>cm</i>	1	pcs.	12.71	#1	12.71	13.60
5G0919491D	Sensor Bracket <i>cm</i>	1	pcs.	12.71	#1	12.71	13.60
5Q0919275B GRU	Sensor Primed <i>ms</i>	1	pcs.	178.20	#1	178.20	190.67
5Q0919133 9B9	Seal Ring Satin Black <i>?</i>	1	pcs.	1.31	#1	1.31	1.40
D 822150A1	Bonding Agent For Plastic <i>cm</i>	1	pcs.	65.18	#1	65.18	69.74
D 180KU2A1	2k-Plastic Adhesive <i>cm</i>	1	pcs.	81.16	#1	81.16	86.84
5G0945095Q	Led Tail Light <i>cm</i>	1	pcs.	591.48	#1	591.48	632.88
5G0853687 2ZZ	Inscription Bright Chrome	1	pcs.	80.16	#1	80.16	85.77
	(Golf) <i>cm</i>						
	LABOU R	4	pcs.	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1 <i>2400</i>	3,200.00	3,424.00

Quotation valid till 09-08-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,788.84	7%	738.42	10,548.84	11,287.26
Total	760.00	9,788.84		738.42	10,548.84	11,287.26

* paint Rear bumper, LHR fender & rear boot .

* Repair LHR fender dent

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TAN
KIAN SOON, JEREMY
(CHEN JIANSHUN)
BLK 316 TAMPINES ST 33
#06-178
SINGAPORE 520316

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

02-08-2021
5211043795
201009404M
30001
2021028790/ 1
02-08-2021
PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SMR8263G	BQ13HZC0	23-01-2020	WWWZZZAUZLW008049	Golf Comfortline 1.4 TSI 92kW DSG	21

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 9001068

5 days

03/08/21 @ 0900

Resurvey before paint