

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1077 G

1 pc	Bootlid weatherstrip X		\$	96.00
1 pc	Bootlid lower garnish <i>repair</i>	<i>Issue</i>	\$	290.00
1 pc	Bootlid CRDi X	<i>hp 9000006</i>	\$	29.00
1 pc	Bootlid emblem X	<i>3 days</i>	\$	27.00
1 pc	End panel inner garnish X	<i>43</i>	\$	74.00
1 pc	Rear bumper de		\$	696.00
1 pc	Rear bumper lower cover <i>sw</i>		\$	206.00
1 pc	Rear bumper inner sponge ?	<i>02/08/21 @ 435</i>	\$	114.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	<i>Reg after repair</i>	\$	58.00
1 pc	Rear bumper reinforcement ?		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00 X		\$	92.00
			\$	2,469.00
Less 10%			\$	246.90
			\$	2,222.10

S/NETT

1 set	Rear bumper clips <i>sw</i>
1 set	Reverse sensor ?
1 set	Bootlid lower garnish clips X
1 set	Bootlid stickers X
1 pc	Rear no. plate with casing X
1 set	End panel inner garnish clips X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	48.00 30
\$	200.00
\$	38.00
\$	100.00
\$	50.00
\$	38.00
\$	50.00 X
\$	120.00 60
\$	180.00 X
\$	850.00 300
\$	600.00 300
\$	80.00 X
\$	4,576.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.