

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1077 G

1 pc	Bootlid weatherstrip <i>X sue</i>	\$	96.00 X
1 pc	Bootlid lower garnish <i>repair</i>	\$	290.00 X
1 pc	Bootlid CRDi <i>an</i>	\$	29.00
1 pc	Bootlid emblem <i>X an</i>	\$	27.00 X
1 pc	End panel inner garnish <i>X an</i>	\$	74.00 X
1 pc	Rear bumper <i>de</i>	\$	696.00
1 pc	Rear bumper lower cover <i>sue</i>	\$	206.00
1 pc	Rear bumper inner sponge <i>? X an</i>	\$	114.00 X
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X an 02/08/21 @ 435</i>	\$	58.00 X
1 pc	Rear bumper reinforcement <i>? X an</i>	\$	607.00 X
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X an</i>	\$	108.00 X
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>? X an</i>	\$	36.00 X
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>? X an</i>	\$	36.00 X
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00 <i>X an</i>	\$	92.00 X
			\$ 2,469.00 <i>131</i>
Less 10%			\$ 246.90 <i>10%</i>
			\$ 2,222.10 <i>837.90</i>

S/NETT

1 set	Rear bumper clips <i>an</i>	\$	48.00 <i>30</i>
1 set	Reverse sensor <i>? X an</i>	\$	200.00 X
1 set	Bootlid lower garnish clips <i>X an</i>	\$	38.00 X <i>30</i>
1 set	Bootlid stickers <i>X an</i>	\$	100.00 X
1 pc	Rear no. plate with casing <i>X an</i>	\$	50.00 X
1 set	End panel inner garnish clips <i>X an</i>	\$	38.00 X
Sundry			\$ 50.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same			<i>837.90</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			<i>30.00</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc			<i>660.00</i>
To putty and spray painting on bootlid lower garnish, rear bumper, end panel			<i>1527.90</i>
To apply rustproofing on the repaired and replaced panels.			<i>20%</i>
			<i>1222.32</i>
			<i>45-1,200</i>
			<i>3 days</i>
			\$ 80.00 X
			\$ 4,576.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.