

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NEO HWEE HWANG
BLK 229 PENDING ROAD #08-205
SINGAPORE 670229

Contact : 81895088, 83556670

TPAXA
Ceilin.

ESTIMATE

Repair Code : CLM15286

Date in : 31/07/2021

Vehicle Num. : SKP4152D

Model : TOYOTA VIOS E GRADE AUTO

Chassis/Eng# : MHFBT9F3806021296/1NZZ072781

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>seufed</i>	1	1138.10	1,138.10 ✓
FRONT LH DOOR BLACK TAPE <i>neu</i>	1	48.00	48.00 ✓
FRONT LH DOOR CHECKER <i>neu</i>	1	183.80	183.80 ✗
FRONT LH DOOR HINGE (LOWER) <i>neu</i>	1	97.50	97.50 ✗
FRONT LH DOOR HINGE (TOP) <i>neu</i>	1	97.50	97.50 ✗
FRONT LH DOOR INNER RUBBER GUIDE STOPPER <i>neu</i>	2	12.60	25.20 ✗
FRONT LH DOOR MECHANISM LOCK <i>neu</i>	1	498.70	498.70 ✗
FRONT LH DOOR OUTER HANDLE <i>neu</i>	1	72.90	72.90 ✗
FRONT LH DOOR WEATHER STRIP <i>ut</i>	1	205.20	205.20 ✓
REAR AXLE <i>neu</i>	1	2882.30	2,882.30 ✗
REAR BUMPER <i>neu</i>	1	521.00	521.00 ✗
REAR BUMPER LH REFLECTOR <i>crackd</i>	1	189.30	189.30 ✓
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	120.10	240.20 ✗
REAR LH DOOR <i>Dented</i>	1	934.90	934.90 ✓
REAR LH DOOR BLACK TAPE <i>neu</i>	1	48.00	48.00 ✓
REAR LH DOOR CHECKER <i>neu</i>	1	183.80	183.80 ✗
REAR LH DOOR GLASS OUTER MOULDING <i>neu</i>	1	75.70	75.70 ✗
REAR LH DOOR GLASS REGULATOR <i>Damp</i>	1	225.20	225.20 ✓

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NEO HWEE HWANG
BLK 229 PENDING ROAD #08-205
SINGAPORE 670229

Contact : 81895088, 83556670

ESTIMATE

Repair Code : CLM15286

Date in : 31/07/2021

Vehicle Num. : SKP4152D

Model : TOYOTA VIOS E GRADE AUTO

Chassis/Eng# : MHFBT9F3806021296/1NZZ072781

REAR LH DOOR GLASS REGULATOR MOTOR <i>new</i>	1	704.80	704.80	+
REAR LH DOOR HINGE (LOWER) <i>} Best</i>	1	97.50	97.50	✓
REAR LH DOOR HINGE (TOP)	1	97.50	97.50	✓
REAR LH DOOR INNER RUBBER GUIDE STOPPER <i>new</i>	1	12.60	12.60	+
REAR LH DOOR INNER TRIM BOARD <i>cancel</i>	1	1270.30	1,270.30	
REAR LH DOOR OUTER HANDLE <i>new</i>	1	72.90	72.90	+
REAR LH DOOR WEATHER STRIP <i>ct</i>	1	205.20	205.20	✓
REAR LH FENDER <i>Repair</i>	1	1021.00	1,021.00	+
REAR LH FENDER INNER PANEL <i>Repair</i>	1	378.90	378.90	+
REAR LH SHOCK ABSORBER <i>new</i>	1	109.80	109.80	+
REAR LH SPORT RIM <i>ct</i>	1	1970.20	1,970.20	
REAR LH WHEEL BEARING <i>change</i>	1	849.90	849.90	
Subtotal before discount			14,457.90	
Percentage discount 25%			3,614.48	
Sub-total 1			10,843.43	
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00	+
REAR LH 185/60R15 TYRE <i>new</i>	1	350.00	350.00	+
REAR LH DOOR INNER SPEAKER <i>cancel</i>	1	250.00	250.00	
			180.	

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

NEO HWEE HWANG

BLK 229 PENDING ROAD #08-205

SINGAPORE 670229

Contact : 81895088, 83556670

ESTIMATE

Repair Code : CLM15286

Date in : 31/07/2021

Vehicle Num. : SKP4152D

Model : TOYOTA VIOS E GRADE AUTO

Chassis/Eng# : MHFBT9F3806021296/1NZZ072781

REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>NW</i>	1	50.00	<i>30</i>	50.00
REAR WINDSCREEN SEAL <i>} new</i>	<i>210</i>	80.00		80.00 X
REAR WINDSCREEN SEALANT	1	80.00		80.00 X
Subtotal before discount				860.00
Percentage discount 0%				0.00
Sub-total 2				860.00
Parts-total				11,703.43

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall windscreen (REAR)

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

3,650.00

Parts & Labour Total

15,353.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

*** This is a computer-generated document which requires no signature.***

page 3

total: 6345.17
 2/5: SK ✓
 H/s 02/08/21.
 07 Days.