

Motor Claim Department
Lompac Insurance
300 Beach Road #17-04/07
The Concourse
Singapore 199555

Repair Estimates

Email: customer_sg@lompac.com

30-Jul-21

Re: SMR638L, Lexus ES250 hit by YN3313H Isuzu
Claim Type: Third Party
Date of Accident: 27 Jul 2021

Dear Sir / Madam

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) <u>Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Remove, Refit Rear Damage Parts - incl: Transfer Bootlid Fittings & Mechanism Replace/Transfer Parking Sensors Transfer Rear Reverse Camera		\$ 2,240.00
2 Cavity Treatment on new parts		\$ 280.00
3 Remove and Refit Rear End Panel Lining and Garnish to facilitate repair		\$ 420.00
4 Remove and Refit Rear Windscreen Glass and Fuel Tank to facilitate Rear Fenders repair		\$ 560.00
5 Repair Both Rear Fender		\$ 1,400.00
6 Conduct Water Seepage test		\$ 210.00
7 Check Wiring, Realign Tailamp and ensure proper functioning		\$ 140.00
8 Spray Painting Rear Floor Panel/Reinforcement		\$ 550.00
9 Spray Painting Complete Rear		\$ 2,200.00

B) <u>Parts</u>	<u>Qty</u>	
1 Rear Bumper	1	\$ 1,030.70
2 Rear Bumper Chrome Trim	1	\$ 418.70
3 LH Reflector	1	\$ 60.70
4 LH Rear Inner Lamp	1	\$ 780.40
5 LH Rear Outer Lamp	1	\$ 850.70
6 Rear Parking Sensor	2	\$ 696.20
7 Rear Boot	1	\$ 818.70
8 Carpet Cover Clip	8	\$ 44.00
9 Rear End Panel	1	\$ 518.70
10 Emblem "LEXUS"	1	\$ 75.70
11 Emblem "ES250"	1	\$ 101.50
12 Emblem "L"	1	\$ 90.40
13 Panel Foam	1	\$ 105.70
14 End Panel Top Garnish	1	\$ 214.70
15 Rear Floor Panel	1	\$ 680.40
16 Rear Boot Chrome	1	\$ 418.40
17 Rear Reinforcement	1	\$ 681.40
18 Luggage Compartment Hinge	2	\$ 335.60
19 Rear Boot Rubber Seal	1	\$ 210.70
20 Rear Boot Plastic Panel	1	\$ 310.40
21 Rear Boot Lock Striker	1	\$ 90.40
22 Luggage Compartment Spring	2	\$ 696.20
23 Rear Boot Top Cover	1	\$ 1,040.70
24 Rear Bonnet Trim Carpet Cover	1	\$ 1,005.70
25 Clip	8	\$ 44.00
26 Number Plate Frame	1	\$ 35.00
27 Number Plate	1	\$ 20.00

TOTAL:		\$ 11,375.70	\$ 8,000.00
Total Labour	:		\$ 8,000.00
Total Parts	:		\$ 11,375.70
			\$ 19,375.70
Plus 7% GST	:		\$ 1,356.30
Grand Total	:		\$ 20,732.00


Should this repair requires any additional parts / labour, we will inform for permission and bill accordingly.

Yours sincerely,

Stephen Yeo

Mobile: +65 9720 0673

Email: stephenyeo@hongseh.com.sg



Hong Seh Motors Pte Ltd
Company Reg. No. 198203320D
10 Fourth Lok Yang Road Singapore 629707
tel +65 6266 1555 fax +65 6265 9595