

LETTER OF DEMAND

26 Nov 2021

Lonpac Insurance (Motor Claim Department)

Re: TP Claim - SMR638L / YN3313H

Date of Accident: 27 Jul 2021

Dear Sir / Madam

I/We wish to inform you repairs to my/our vehicle <u>SMR638L</u> has been completed to my/our satisfaction by M/s <u>Hong Seh Motors Pte Ltd</u>. I/We therefore propose to claim from you as follow:

1. Cost of Repair S\$ 10,067.95

Total: \$\$ 11,267.95

w/GST 7% **S\$ 12,056.71**

Thank you,

Yours faithfully

For and on behalf of Hong Seh Motors Pte Ltd owner of SMR638L



AUTHORIZATION TO ACT

I, <u>Tan Wee Meng Edward</u> ("the third party claimant"),
owner of <u>Lexus ES250 SMR638L</u> (vehicle no.) hereby authorize <u>Hong Seh Motors</u>

<u>Pte Ltd</u> ("the workshop") to act for me with respect to my claim for
repair costs, loss of use ("claim") for my <u>Lexus ES250 SMR638L</u> (vehicle no.) that was
damaged pursuant to the accident which occurred on <u>27/07/2021</u> (date) involving vehicle

<u>YN3313H</u> ("the accident").

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner/ insurers of the other vehicle/s is/are concerned.

Date this 24 (day) of Nov (month) 20 21 (year)

Signature of the "Third Party Claimant"

Signature and stamp of the "Workshop"

GST Reg. No.: M2-0055566-0

Invoice Details

: Lonpac Insurance

Service Order Number

Customer

•

WIP-11507

L006

Singapore 068811

Invoice Date 26/11/21 Document Number

2021220655

Vehicle Details

Model

Mileage (km)

Registration Number

Chassis Number

Lexus GS250

34,863

SMR638L

JTHB11B1802020811

Category	Description	Qty	Unit Price	Price	Disc %	Amount
		(Unit)			54 /4	, sinount
Labor	Remove/Refit Rear Damaged Parts	1	2,000.00	2,000.00		1,750.00
Labor	Cavity Treatment On New Parts	1	50.00	50.00		50.00
Labor	Remove/Refit Rear End Panel Lining/Garnish	1	100.00	100.00		100.00
Labor	Conduct Water Seepage Test	1	30.00	30.00		30.00
Labor	Check Wiring,Realign Tail-lamp Ensure	1	50.00	50.00		50.00
Labor	Spray Paint Complete Rear	1	1,250.00	1,250.00		1,000.00
					SubTotal:-	2,980.00
ltem	Rear Bumper	1	1,030.70	1,030.70	10.00	927.63
ltem	Rear Bumper Chrome Trim	1	418.70	418.70	10.00	376.83
ltem	LH Reflector	1	60.70	60.70	10.00	54.63
ltem	LH Rear Inner Lamp	1	780.40	780.40	10.00	702.36
ltem	LH Rear Outer Lamp	1	850.70	850.70	10.00	765.63
ltem	Rear Parking Sensor	2	250.00	500.00	10.00	450.00
ltem	Rear Boot	1	818.70	818.70	10.00	736.83
ltem	Carpet Cover Clip	8	2.50	20.00	10.00	18.00
ltem	Rear End Panel	1	518.70	518.70	10.00	466.83
item	Emblem "L"	1	90.40	90.40	10.00	81.36
ltern	Emblem "ES250"	1	101.50	101.50	10.00	91.35
ltem	Emblem "LEXUS"	1	75.70	75.70	10.00	68.13
ltem	Panel Foam	1	105.70	105.70	10.00	95.13
ltem	End Panel Top Garnish	1	214.70	214.70	10.00	193.23
ltem	Rear Boot Chrome	1	418.40	418.40	10.00	376.56
ltem	Rear Reinforcement	1	681.40	681.40	10.00	613.26
ltem	Rear Boot Rubber Seal	1	210.70	210.70	10.00	189.63
ltem	Rear Boot Plastic Panel	1	310.40	310.40	10.00	279.36
ltem	Rear Boot Top Cover	1	588.00	588.00	10.00	529.20
ltem	Clip	8	3.75	30.00	10.00	27.00
ltem	Number Plate Frame	1	30.00	30.00	10.00	27.00
ltem	Number Plate	1	20.00	20.00	10.00	18.00
					Sub Total:-	7,087.9
Clause:-		 	_l	1,	1	1,001.00
Kindly remove all your belongings when sending your car for servicing or repairs. Any personal Total SGD :						10,067.98
belongings left in the car or at our premises are at your own risk. The management is NOT liable for any 7% GST						704.76
	. Any objections or queries to the validity of these charges must be ma				•	
from the date of the invoice otherwise it is assumed the repair is deemed satisfactory. Payment is required Amount Due (SGD)						i .

after 2 weeks from date of Invoice. Vehicle must be collected within 7 working days upon completion of job, otherwise a minimum store rent of \$35/day not inclusive of insurance will be imposed.

Hong Seh Motors Pte Ltd Company Reg. No. 198203320D

10 Fourth Lok Yang Road Singapore 629707 tel +65 6266 1555 fax +65 6265 9595

