



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21008129/Uuf3e2	
			Date: 01/10/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 9001C	Veh. Inspected	SLN 4981B	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D16292108	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	02/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZSU600076678	Colour	PURPLE	
Odometer	36985 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	CONTINENTAL	7 mm	
L/H Front Tyre	235/55 R18	CONTINENTAL	7 mm	
R/H Rear Tyre	235/55 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	235/55 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2021	Inspection Date	03/08/2021	
Survey held at	Blk 15 Kaki Bkt Road 4, Bartley Biz Centre, #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	