

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21008133/AES3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SDT383S**Insured Vehicle No :** SJX2824G

Date of Loss: 01/08/2021

Nature of Claim:

TP

Claim No: 6136074598SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDT383S**

Make &amp; Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)

Engine No: CZE844611

Reg. Date: 31/10/2018 (Man. Year: 2018)

Chassis No: WAUZZZGA8KA005991

Colour: Orange

Odometer: 37540 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,758.00	888.40	6,869.60	88.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	1,602.00	2,550.00	61.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,910.00</b>	<b>2,490.40</b>	<b>9,419.60</b>	<b>79.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	833.70	174.33	659.37	79.09
<b>Nett Amount (S\$)</b>	<b>12,743.70</b>	<b>2,664.73</b>	<b>10,078.97</b>	<b>79.09</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,966.73</b>		

INSPECTION

Date of Assignment: 06/08/2021

Date Inspected: 06/08/2021

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	894.00 FS	*- FS
2	1		*FRONT BUMPER AIR GRILLE -RH	Cut	169.00 FS	*135.20 FS
3	1		*FRONT BUMPER AIR GRILLE END CAP -RH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Cut	299.00 FS	*238.80 FS
5	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
6	1		*FRONT BUMPER WHEEL SPOILER RH	Not Necessary	34.00 FS	*- FS
7	1		*FRONT BUMPER ADAPTER -RH	Not Necessary	42.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	36.00 FS	*- FS
9	2		*FRONT BUMPER WHEEL ARCH COVER -LH/RH	Necessary	644.00 FS	*514.40 FS
10	1		*FRONT HEADLIGHT MOUNTING -RH	Not Necessary	118.00 FS	*- FS
11	1		*FRONT HEADLIGHT-RH	Not Necessary	4,915.00 FS	*- FS
12	1		*FRONT HEADLIGHT LIFT CYLINDER -RH	Not Necessary	142.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>7,758.00      888.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,152.00</b>	<b>1,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >