

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0619/2021/TF
DATE : 2-Aug-21
WIP : 38005

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SJX 2824 G

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LIM KWAN HOWE, ANDY
ADDRESS : 52 HILLCREST ROAD
SINGAPORE 288923
TELEPHONE : HP +65 91283078
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800130049-02
VEHICLE NO : **SDT 383 S**
MODEL CODE : AUDI Q2 1.4 TFSI COD S TRONIC
MODEL YEAR : 31/10/2018
ENGINE NO : CZE 844611
CHASSIS NO : WAUZZZGA8KA005991
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-21
PLACE OF ACCIDENT : OUTSIDE OF 1 WATTEN RISE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDT 383 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDT 383 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Rep</i>	1	\$	894.00	<i>✓</i>
2	FRONT BUMPER AIR GRILLE - RH <i>ut</i>	1	\$	169.00	<i>✓</i>
3	FRONT BUMPER AIR GRILLE END CAP - RH <i>new</i>	1	\$	59.00	<i>✓</i>
4	FRONT BUMPER SPOILER <i>ut</i>	1	\$	299.00	<i>✓</i>
5	FRONT BUMPER LOWER CLOSING ELEMENT <i>new</i>	1	\$	156.00	<i>✓</i>
6	FRONT BUMPER WHEEL SPOILER - RH <i>new</i>	1	\$	34.00	<i>✓</i>
7	FRONT BUMPER ADAPTER - RH <i>new</i>	1	\$	42.00	<i>✓</i>
8	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$	36.00	<i>✓</i>
9	FRONT BUMPER WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$	644.00	<i>✓</i>
10	FRONT HEADLIGHT MOUNTING - RH <i>new</i>	1	\$	118.00	<i>✓</i>
11	FRONT HEADLIGHT - RH <i>new</i>	1	\$	4,915.00	<i>✓</i>
12	FRONT HEADLIGHT LIFT CYLINDER - RH	1	\$	142.00	<i>✓</i>
13	SUNDRIES		\$	250.00	<i>?</i>
TOTAL SPARE PARTS			:	\$	7,758.00
TOTAL LABOUR CHARGES			:	\$	4,152.00
GRAND TOTAL			:	\$	11,910.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *06/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT