



# 南方摩哆 Southern Motor

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

31-Jul-21

AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore (079120)

Dear Sirs,

**RE: Cost of repair to Yamaha Vixion R Manual – FBS2519J**

1pc of Front Mudguard	S\$	95.00
1pc of Front Brake Disk		185.00
1pc of Handle Bar		65.00
1pc of Clutch Lever		25.00
1pc of Handle Balancer		25.00
1pc of Front Signal Light		65.00
1pc of Front Fairing		225.00
1pc of Fuel Tank Cover		385.00
1pc of Gear Lever		90.00
1pc of Front Footrest		45.00
1pc of Side Stand		58.00
1Set of Rear Footrest		65.00
1pc of Exhaust Pipe Cover		160.00
		<hr/> 1,488.00
	Less 10%	148.80
	Nett	<hr/> 1,339.20
	Transport	30.00
	Alignment Fork	95.00
	Alignment Fork Rim	65.00
	Jack Rear Body	120.00
	Rear Givi Box	180.00
	Labor	250.00
		<hr/> <u>\$2,079.20</u>

Yours Faithfully,  
Southern Motor

Date: 31 Jul 2021

Southern Motor  
Blk 1006 Bukit Merah Lane 2  
#01-10  
Singapore 159762

Motor Claims Department  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore 079120

Dear Sirs,

RE: ACCIDENT INVOLING FBS2519J AND SKX4505C ALONG  
AYE/MCE before Clementi Ave 6 Exit ON 15-07-2021 AT 09:00AM

Please be informed that the above-said motorcycle bearing registration no: FBS2519J was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,

  
Enc.