



南方摩哆 Southern Motor

Business Reg. No: 234147/001.
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762.
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

31-Jul-21

AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to Yamaha Vixion R Manual – FBS2519.J

1pc of Front Mudguard	BR	SS	95.00	78
1pc of Front Brake Disk	X mm		185.00	X
1pc of Handle Bar	BT		65.00	
1pc of Clutch Lever	BR		25.00	
1pc of Handle Balancer	cut		25.00	
1pc of Front Signal Light	BR		65.00	
1pc of Front Fairing	cut		225.00	168
1pc of Fuel Tank Cover	cut		385.00	288
1pc of Gear Lever	BR		90.00	
1pc of Front Footrest	BT		45.00	
1pc of Side Stand	BT		58.00	
1 Set of Rear Footrest	BR		65.00	
1pc of Exhaust Pipe Cover	cut		160.00	

1132
-10%
1018.80

Less 10%	148.80
Nett	1,339.20
Transport	30.00
Alignment Fork	95.00
Alignment Fork Rim	65.00
Jack Rear Body	120.00
Rear Givi Box	180.00
Labor	250.00

Steve (LKIK) = 1628.80 \$2,079.20

21/8/21, 4:30pm

8372 8813

L/S - 1303.24
= 1300

W/L
L/S
M BL
4 4/5

LKK Auto Consultants hereby notify
the Repairer of the following:

- To repair or replace the body painting
- To repair or replace the body assembly
- To repair or replace the body parts
- To repair or replace the body structure
- To repair or replace the body frame
- To repair or replace the body chassis
- To repair or replace the body engine
- To repair or replace the body transmission
- To repair or replace the body suspension
- To repair or replace the body steering
- To repair or replace the body braking
- To repair or replace the body lighting
- To repair or replace the body electrical
- To repair or replace the body exhaust
- To repair or replace the body accessories

Authorised by:

Signature:

Date:

Yours Faithfully,
Southern Motor