

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6420 X

1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>by</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>x</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>?</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>?</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>?</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>x</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>x</i>
		\$	1,861.00
		\$	186.10
		\$	1,674.90

Less 10%

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>30.00</i>
1 set	Reverse sensor	\$	280.00 <i>200.00</i>
	Sundry	\$	50.00 <i>x</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 <i>30.</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>x</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$	550.00 <i>200</i>
	To putty and spray painting on rear bumper, end panel	\$	400.00 <i>200</i>
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 <i>x</i>
		\$	3,382.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749
wp 3/8/21 R1535
1/5 Resurvey after repair
2 days