

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

29-Jul-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6420 X

1 pc	Rear bumper	\$	696.00	de
1 pc	Rear bumper lower cover	\$	206.00	hy
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	X
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	X
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	X
		\$	1,861.00	696
		\$	186.10	
		\$	1,674.90	626.40

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### S/NETT

1 set	Rear bumper clips	\$	48.00	30mm
1 set	Reverse sensor	\$	280.00	200mm 230
Sundry		\$	50.00	X mm
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	30.
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	X mm
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		\$	550.00	200 200
To putty and spray painting on rear bumper, end panel		\$	400.00	4/5/1000
To apply rustproofing on the repaired and replaced panels.		\$	80.00	2days
		\$	3,382.90	430

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749  
WP 3/8/21 R1535  
4/5 Resurvey after repair  
2 days