

ASS. REC. BY:

REF:

A161

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK 130H Yr Regn: 10, 09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 520i cc 1995Colour: M. D. Blue A/C: Insured / Std / NI / NASp. Reading: 160625 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA NT120X0 CX30526Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 12/10/17 D.O.I. 25/10/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/10 All parts takenUNCOMPENSATED Up to 8,100.00CHUCK TOWNS: 8,704.8613,879.51 / 63.15%

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

\$ - RS - \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17020484/Kha3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 25-10-2017	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJQ 9382E	Veh. Inspected	SLK 130H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/10/2017	Inspection Date	25/10/2017
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not Withdraw
61 Sep 87
Heavy After Rain
Today*

CJ PENINSULA RESOURCES PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 24-10-17

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: BMW 523i / SLK130H	
1 pc	rear boot lid	<i>R</i> 1,700.00 <i>L</i>
1 pc	rear boot emblem logo	<i>SD</i> <i>REC</i> 72.30 <i>X</i>
1 pc	rear boot open latch	<i>Sm</i> 196.60 <i>X</i>
1 pc	rear boot number plate lamp	<i>Sm</i> 50.00 <i>X</i>
1 pc	rear boot outer garnish	<i>Sm</i> 399.60 <i>X</i>
1 pc	rear boot lock	<i>R</i> 167.40 <i>X</i>
1 pc	rear boot lock catch	<i>R</i> 83.70 <i>X</i>
1 pc	rear bumper (M-tech version)	<i>Bea</i> 2,780.00 <i>L</i>
25 pcs	rear bumper clips @ 4.80	<i>Sm</i> 120.00 <i>L</i>
2 pcs	rear bumper bracket @ 60.00	120.00 <i>?</i>
2 pcs	rear bumper side bracket @ 100.00	200.00 <i>?</i>
1 pc	rear bumper reinforcement	720.00 <i>?</i>
2 pcs	rear bumper reinforcement brackets @ 347.37	694.74 <i>?</i>
1 pc	rear bumper inner pad	289.00 <i>?</i>
1 pc	rear bumper lower kit	<i>R</i> 855.00 <i>L</i>
1 pc	rear bumper sponge	367.00 <i>?</i>
1 pc	rear bumper top garnish	283.00 <i>?</i>
1 pc	rear bumper tow cover	<i>Sm</i> 84.00 <i>X</i>
4 pcs	rear bumper reverse sensor @ 568.00	<i>Ad</i> 1,136.00 <i>L</i>
4 pcs	rear bumper reverse sensor garnish @ 85.00	340.00 <i>?</i>
1 pc	rear end panel	<i>B</i> 844.00 <i>L</i>
1 pc	rear end panel garnish	680.00 <i>?</i>
1 pc	rear exhaust silencer	2,300.00 <i>?</i>
2 pcs	rear exhaust silencer rubber mount @ 54.00	<i>Sm</i> 108.00 <i>X</i>
1 pc	rear exhaust heat shield	374.00 <i>?</i>
2 pcs	rear tail lamp assy @ 860.00	<i>Gr</i> 1,720.00 <i>L</i>
2 pcs	front seat head rest @ 1,652.00	3,304.00 <i>?</i>
	sub-total	19,988.34
	less 10%	1,998.83
	sub-total	17,989.51

Balance brought forward

17,989.51

To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.

1000
1,600.00

To check wiring system and reset ECU.

200 100.00

To apply putty and spray painting on affected areas.

900 1,200.00

To apply rust proofing on affected areas.

600 150.00

To apply waterproof sealant on affected areas.

300 150.00

To install reverse sensor and reset ECU programme.

1200 300.00

To remove carpet & trimming to enable repair.

800 120.00

To carry out exhaust works.

800 150.00

To reset SRS system.

1200 220.00

Total

21,979.51

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG17020484/Kha3

05 JANUARY 2018

POPULAR RENT A CAR PTE LTD
501 GUILLEMARD ROAD
SINGAPORE 399840

Dear Sir/Madam,

ACCIDENT INVOLVING SJQ 9382E AND SCK 130H ON 12.10.17

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Vic (LKKAUTO)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Thursday, 28 February, 2019 11:42 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: Our Ref: 3941753711SG-003 || Accident Involving SJQ9382E / SLK130H on 12/10/2017 LKK REF CC4/AIG17020484/Kha3

Hi Vic

Referring to your email below.

Since there is no development from TP repairer since 12/01/2018, please submit WP report & invoice for closure to matter. We will revisit this matter if fresh developments arise.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Thursday, January 31, 2019 5:31 PM
To: Tan, Bennie-WZ
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Our Ref: 3941753711SG-003 || Accident Involving SJQ9382E / SLK130H on 12/10/2017 LKK REF CC4/AIG17020484/Kha3

Dear Bennie,

We refer to your below email.

Please be informed that we are still pending finalization confirmation from TP repairer.

Our last correspondence with TP via email was on 12/01/2018.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth- Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Tan, Bennie-WZ [<mailto:Bennie-WZ.Tan@aig.com>]

Sent: Thursday, 31 January, 2019 4:47 PM

To: CS A Team

Subject: Our Ref: 3941753711SG-003 || Accident Involving SJQ9382E / SLK130H on 12/10/2017

Hi LKK

Referring to the above under your care.

Kindly let us have an update on the last correspondent / developments to this matter.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or

printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2017 Edit Reg		25 Oct 2017 00:00 Edit Adj Rpt	\$48,100.00 Edit Estimates	\$48,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	POPULAR RENT A CAR PTE LTD, Co. Reg. No.: 199608195Z								
Main Claimant:	CJ PENINSULA RESOURCES PTE LTD, Co. Reg. No.: 201209712N								
Vehicle Reg. No.:	SLK130H	Date of Loss:	12/10/2017 08:00 - :59 [96 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3941753711SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SJQ9382E	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK130H (3941753711SG)
[SJQ9382E]
TP
CJ PENINSULA RESOURCES PTE LTD
Oct 12 2017 8:00AM
[POPULAR RENT A CAR PTE LTD]
Autoworx House - Sin Ming

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	12/01/18 09:39	Chassis Number														<input checked="" type="checkbox"/>				
2	12/01/18 09:39	Odometer Reading														<input checked="" type="checkbox"/>				
3	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
4	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
5	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
6	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
7	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
8	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
9	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
10	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
11	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
12	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
13	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
14	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
15	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
16	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
17	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
18	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
19	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
20	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
21	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
22	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
23	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
24	12/01/18 09:39	General View														<input checked="" type="checkbox"/>				
Documentation															1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	25/10/17 19:17	ACKNOWLEDGEMENT EMAIL TO AIG DD 25.10.2017																		
2	25/10/17 19:17	EMAIL FROM AIG DD 25.10.2017																		
3	25/10/17 19:17	NOTIFICATION FROM WORKSHOP + TP GIA REPORT																		
4	05/01/18 11:25	LETTER TO OI																		
5	28/02/19 13:39	EMAIL FROM AIG																		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	26/10/17 09:54	OI GIA report																		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	↕
--	---

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17020484/KHA3Q2

Date: 04/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK130H

Insured Vehicle No : SJQ9382E

Date of Loss: 12/10/2017

Nature of Claim: TP

Claim No: 3941753711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK130H**

Make & Model: BMW 520i, 2.0 (A)

Engine No: HIDDEN

Reg. Date: 01/10/2009 (Man. Year: 2009)

Chassis No: WBANT120X0CX30528

Colour: Metallic Dark Blue

Odometer: 160625 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Falken 7 mm

Rear Left Side: Falken 7 mm

Front Right Side: Falken 7 mm

Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,989.51	7,728.30	10,261.21	57.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	2,410.00	1,580.00	39.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,979.51	10,138.30	11,841.21	53.87
Approved Total (Overridden) (S\$)		8,100.00		
Nett Amount (S\$)	21,979.51	8,100.00	13,879.51	63.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/10/2017

Date Inspected: 25/10/2017 Inspected At:

Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,700.00 FL	*1,700.00 FL
2	1		*REAR BOOT EMBLEM LOGO	Serviceable	72.30 FL	*- FL
3	1		*REAR BOOT OPEN LATCH	Serviceable	196.60 FL	*- FL
4	1		*REAR BOOT NUMBER PLATE LAMP	Serviceable	50.00 FL	*- FL
5	1		*REAR BOOT OUTER GARNISH	Serviceable	399.60 FL	*- FL
6	1		*REAR BOOT LOCK	Repair	167.40 FL	*- FL
7	1		*REAR BOOT LOCK CATCH	Repair	83.70 FL	*- FL
8	1		*REAR BUMPER (M-TECH VERSION)	Buckled	2,780.00 FL	*2,780.00 FL
9	1		*REAR BUMPER CLIPS (25 PCS)	Necessary	120.00 FL	*120.00 FL
10	2		*REAR BUMPER BRACKET	*Check	120.00 FL	*- FL
11	2		*REAR BUMPER SIDE BRACKET	*Check	200.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	*Check	720.00 FL	*- FL
13	2		*REAR BUMPER REINFORCEMENT BRACKETS	*Check	694.74 FL	*- FL
14	1		*REAR BUMPER INNER PAD	*Check	289.00 FL	*- FL
15	1		*REAR BUMPER LOWER KIT	Bent	855.00 FL	*855.00 FL
16	1		*REAR BUMPER SPONGE	*Check	367.00 FL	*- FL
17	1		*REAR BUMPER TOP GARNISH	*Check	283.00 FL	*- FL
18	1		*REAR BUMPER TOW COVER	Serviceable	84.00 FL	*- FL
19	2		*REAR BUMPER REVERSE SENSOR	Dented (1 PCS ONLY)	1,136.00 FL	*568.00 FL
20	4		*REAR BUMPER REVERSE SENSOR GARNISH	*Check	340.00 FL	*- FL
21	1		*REAR END PANEL	Bent	844.00 FL	*844.00 FL
22	1		*REAR END PANEL GARNISH	*Check	680.00 FL	*- FL
23	1		*REAR EXHAUST SILENCER	*Check	2,300.00 FL	*- FL
24	2		*REAR EXHAUST SILENCER RUBBER MOUNT	Serviceable	108.00 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD	*Check	374.00 FL	*- FL
26	2		*REAR TAIL LAMP ASSY	Cut	1,720.00 FL	*1,720.00 FL
27	2		*FRONT SEAT HEAD REST	*Check	3,304.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	19,988.34	8,587.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,998.83	858.70
Total Parts (\$\$)	17,989.51	7,728.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	1,000.00
2	TO CHECK WIRING SYSTEM AND RESET ECU	New	100.00	20.00
3	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	900.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	30.00
6	TO INSTALL REVERSE SENSOR AND RESET ECU PROGRAMME	New	300.00	120.00
7	TO REMOVE CARPET & TRIMMING TO ENABLE REPAIR	New	120.00	80.00
8	TO CARRY OUT EXHAUST WORKS	New	150.00	80.00
9	TO RESET SRS SYSTEM	New	220.00	120.00
Gross Labour Cost (S\$)			3,990.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >