

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not withstanding
11 Sep 87
Recovery After Pain
Today*

CJ PENINSULA RESOURCES PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 24-10-17

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: BMW 523i / SLK130H	
1 pc	rear boot lid	<i>R</i> 1,700.00
1 pc	rear boot emblem logo	<i>mc</i> 72.30
1 pc	rear boot open latch	<i>sn</i> 196.60
1 pc	rear boot number plate lamp	<i>sn</i> 50.00
1 pc	rear boot outer garnish	<i>sn</i> 399.60
1 pc	rear boot lock	<i>n</i> 167.40
1 pc	rear boot lock catch	<i>n</i> 83.70
1 pc	rear bumper (M-tech version)	<i>Bua</i> 2,780.00
25 pcs	rear bumper clips @ 4.80	<i>mc</i> 120.00
2 pcs	rear bumper bracket @ 60.00	120.00
2 pcs	rear bumper side bracket @ 100.00	200.00
1 pc	rear bumper reinforcement	720.00
2 pcs	rear bumper reinforcement brackets @ 347.37	694.74
1 pc	rear bumper inner pad	289.00
1 pc	rear bumper lower kit	<i>A</i> 855.00
1 pc	rear bumper sponge	367.00
1 pc	rear bumper top garnish	283.00
1 pc	rear bumper tow cover	<i>sn</i> 84.00
4 pcs	rear bumper reverse sensor @ 568.00	<i>nd</i> 1,136.00
4 pcs	rear bumper reverse sensor garnish @ 85.00	340.00
1 pc	rear end panel	<i>B</i> 844.00
1 pc	rear end panel garnish	680.00
1 pc	rear exhaust silencer	2,300.00
2 pcs	rear exhaust silencer rubber mount @ 54.00	<i>sn</i> 108.00
1 pc	rear exhaust heat shield	374.00
2 pcs	rear tail lamp assy @ 860.00	<i>sn</i> 1,720.00
2 pcs	front seat head rest @ 1,652.00	3,304.00
	sub-total	19,988.34
	less 10%	1,998.83
	sub-total	17,989.51

Balance brought forward	17,989.51
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1000 1,600.00
To check wiring system and reset ECU.	200 100.00
To apply putty and spray painting on affected areas.	800 1,200.00
To apply rust proofing on affected areas.	600 150.00
To apply waterproof sealant on affected areas.	300 150.00
To install reverse sensor and reset ECU programme.	1200 300.00
To remove carpet & trimming to enable repair.	800 120.00
To carry out exhaust works.	800 150.00
To reset SRS system.	1200 220.00
Total	21,979.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: