

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0602/2021/ZK
DATE : 26-Jul-21
WIP : 36879

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/07/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 Sunday.

Johnny Boo 17 Sep 21

OWNER'S NAME : MR ABHISHEK GARG
ADDRESS : 132 TANJONG RHU ROAD PEBBLE BAY
#15-12
SINGAPORE 436919
TELEPHONE : HP +65 85710400
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900171616-01
VEHICLE NO : **SMP 5817 P**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : Q5 SPORT 2.0 TFSI
ENGINE NO : DAX 058089
CHASSIS NO : WAUZZZFVYK2123257
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jul-21
PLACE OF ACCIDENT : 130 TANJONG RHU ROAD PEBBLE BAY CONDOMINIUM CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5817 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
2	TO RENEW LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	300.00	
3	TO INSTALL SOLAR FLIM FOR LHS SIDE 1/4 GLASS	S/N \$	400.00	
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	S/N \$	200.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 2,660.00	\$ 360.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5817 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		<i>\$ 360.00</i>
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST , HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.	S/N \$	400.00	<i>\$ 280.00</i>
8	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW LHS REAR DOOR.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	6,400.00	<i>\$ 1,500.00</i>
9	TO RESPRAY REAR BUMPER , LHS REAR FENDER , LHS REAR DOOR , BOTH REAR WHEEL ARCH TRIMS,DOOR COVER, LHS SILL PANEL , ROOF CHANNEL , DRAIN CHANNEL,DOOR ENTRANCE AND REAR END PANELLING.	\$	7,100.00	<i>\$ 2,300.00</i>
10	TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	<i>\$ 240.00</i>
11	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	<i>\$ 192.00</i>
TOTAL LABOUR CHARGES		:	\$ 18,672.00	<i>\$ 4,872.00</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5817 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER GUIDE SECTION - LH	1	\$ 84.00		
2	REAR WHEEL ARCH COVER - LH / RH	1	\$ 1,166.00	\$	932.80
3	REAR FENDER - LH	1	\$ 4,902.00		
4	REAR SIDE WINDOW - LH	1	\$ 832.00		
5	REAR SIDE WINDOW PRIMER	1	\$ 20.00		
6	REAR DOOR - LH	1	\$ 4,085.00	\$	3,268.00
7	REAR DOOR SEAL - LH	1	\$ 205.00	\$	164.00
8	REAR DOOR BONDING AGENT	1	\$ 49.00		
9	REAR DOOR CLEANING SOLUTION	1	\$ 68.00		
10	REAR DOOR APPLICATOR	1	\$ 8.00		
11	SEALING STRIP	1	\$ 17.00		
12	GROMMET	1	\$ 9.00		
13	REAR DOOR CATCH - LH	1	\$ 146.00	\$	116.40
14	REAR DOOR COVER - LH	1	\$ 689.00	\$	551.20
15	REAR ALUMINIUM RIM -LH	1	\$ 1,821.00		
16	1/4 GLASS SEALANT	1	\$ 100.00		
17	ACRYLIC SEALANT	1	\$ 180.00		
18	CAVITY WAX	1	\$ 140.00		
19	STONE CHIP	1	\$ 180.00		
20	METAL FILLER POWER	1	\$ 280.00		
21	SUNDRIES	S/N	\$ 400.00	\$	9.28
TOTAL SPARE PARTS		:	\$ 15,381.00	\$	5,041.68
TOTAL LABOUR CHARGES		:	\$ 18,672.00	\$	4,872.00
GRAND TOTAL		:	\$ 34,053.00	\$	9,913.68

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-02/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT