

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Jul 2021 13:34	Clim Veh Model Changed		[] Merimen Administrator
2	26 Jul 2021 13:34	Clim Created	Reg No: SMP5817P. Policy No: 1900171616-01. Acct Date: 2021/07/25. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R217Q0001	[I] Merimen Administrator
3	02 Aug 2021 16:24	Clim Registration Modified	Init.Est.->5,000 - 6,000.	[I] Low, Xianyu
4	03 Aug 2021 10:53	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
5	03 Aug 2021 10:53	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
6	03 Aug 2021 10:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
7	03 Aug 2021 10:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/08/13	[A] CELINE FONG
8	03 Aug 2021 10:53	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
9	03 Aug 2021 10:53	Clim Registration Modified	Rep:1137->200611.	[A] CELINE FONG
10	03 Aug 2021 10:53	Clim Veh Model Changed	(206231) AUDI Q5 SPORT 2.0 TFSI QU S TRONIC (A).	[A] CELINE FONG
11	03 Aug 2021 10:54	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
12	03 Aug 2021 12:05	Adj Rpt Initiated		[A] HUEY YON
13	03 Aug 2021 12:05	Insured Phone No Updated	[6585710400] -> [+656585710400]	[A] HUEY YON
14	03 Aug 2021 12:05	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
15	03 Aug 2021 12:05	Clim Dtl Modified	JPJ Reg. Date: -> 2019/09/30.	[A] HUEY YON
16	03 Aug 2021 12:05	Clim Details Notified		[A] HUEY YON
17	03 Aug 2021 13:54	Clim Registration Modified	Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
18	04 Aug 2021 09:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/08/13	[A] SHIAU CHAN
19	04 Aug 2021 09:09	Adj Mandate Request	Cur.Reg:11688.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
20	04 Aug 2021 13:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/08/13. Mandate Remarks: Vehicle may commence repair *take more photos for REAR DOOR COVER-LH* Checked and Supplementary items to resurvey with CLEAR photos f or damage and consistency. Before paint photos	[I] Lim, Kok-Chong
21	04 Aug 2021 13:38	Adj Mandate Set	Approved:11017.00:Vehicle may commence repair *take more photos for REAR DOOR COVER-LH* Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts requ	[I] Lim, Kok-Chong

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2713991	03 Aug 2021 12:05:36	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMP5817P		11.00

