

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SJJ5907E ✓
Chassis No:
Engine No:

Report No :
Date : 31.07.2021

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper	Damaged	\$ 1,455.00	\$ 1,309.50 / cut 950 DD
2	2	Rear Bumper Bracket	Necessary	\$ 198.00	\$ 178.20 / XNA X SVC
3	1	Rear Reinforcement	Dented	\$ 677.00	\$ 609.30 / XNA
4	1	Rear End Panel	Impacted	\$ 780.00	\$ 702.00 / 00. SSO
5	1	Rear Boot	Damaged	\$ 1,677.00	\$ 1,509.30 / cut 780 DD
6	1	Rear Boot Weather Strip	Necessary	\$ 188.00	\$ 169.20 / Xr
7	1	Rear End Panel Garnish	Damaged	\$ 295.00	\$ 265.50 / cut 125
8	1	Rear Boot Lock	Jammed	\$ 190.00	\$ 171.00 / DIS
9	1	Rear Boot Lock Hinge	Distorted	\$ 110.00	\$ 99.00 / Xr
10	1	Rear Boot Floorboard	Broken	\$ 1,430.00	\$ 1,287.00 / X not com
11	1	Rear "H" Logo	Necessary	\$ 110.00	\$ 99.00 / HPC 38
12	1	Rear Boot Lamp Left	Damaged	\$ 455.00	\$ 409.50 / cra 293
13	1	Rear Boot Lamp Right	Damaged	\$ 455.00	\$ 409.50 / cra 293
14	1	Rear Tail Lamp Left	Damaged	\$ 690.00	\$ 621.00 / cra 300,
15	1	Rear Tail Lamp Right	Damaged	\$ 690.00	\$ 621.00 / X not com
16	1	Rear Reverse Sensor	Faulty	\$ 250.00	\$ 225.00 / 200 cut (SN)
				\$ 9,650.00	\$ 8,685.00

Total (Parts): \$ 9,650.00 -20% \$ 8,685.00 - 20%

Labour Charges

26	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ 1,000.00	400
27	To apply anti rust coat and affected areas	\$ 120.00	30
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis align	\$ 800.00	400 200
30	Spray painting for Rear Portions affected parts	\$ 1,000.00	400
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ 120.00	20
33	3D Wheel Alignment	\$ -	
34	To Apply Waterproofing sealer on End Panels	\$ 120.00	30

Total Labour: \$ 3,340.00
1310

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 12,025.00

LKK Auto Consultant Less 20% \$ 9,620.00

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

AMM PTE LTD

Thirvan Lkh
wp 4 days
4/8/21 1715
82235769
thirvan@lkh auto.com

Page 2 of 3