

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/WONG SANG PANG
	Reg No/Reg Date	SJH1383C / 22/01/201
	Date In/Mileage	03/08/2021/ 0
	Chassis No	JMYXTGF3WGZ002267
	Engine No	4B12QR5032
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/08/2021/ 13:07	QUK	282 / Kevin Leong	13842			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPALCE FRT BUMPER, FRT RH FENDER, SUPPORT & AFFECTED AREA								
REPAIR ON FRT LH FENDER								
E PNT98000								1400.00
PAINT WORK FRT BUMPER, FRT BOTH FENDER & FRT RH DOOR								
E PNT88000								120.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO TOP UP AIRCON GAS								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								30.00
TO TRANSFER FRT RH RIM INCLUDING BALANCING								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME								
M SUNDRY								320.00
TO APPLY ZERTONA COATING ON AFFECTED AREA								
M SUNDRY								30.00
SUNDRIES								
M	HEADLAMP ASSY,LH				1.00	2135.00	23.00	1643.95
M	HEADLAMP ASSY,RH				1.00	2135.00	23.00	1643.95
M	BRACKET,FR BUMPER SIDE,LH				1.00	18.00	23.00	13.86
M	BRACKET,FR BUMPER SIDE,RH				1.00	18.00	23.00	13.86
M	EXTENSION,FR BUMPER				1.00	428.00	23.00	329.56
M	COVER,HEADLAMP SUPT PANEL				1.00	50.00	23.00	38.50
M	GRILLE ASSY,RADIATOR				1.00	572.00	23.00	440.44
M	COVER,FR BUMPER				1.00	25.00	23.00	19.25

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/WONG SANG PANG
	Reg No/Reg Date	SJH1383C / 22/01/201
	Date In/Mileage	03/08/2021/ 0
	Chassis No	JMYXTGF3WGZ002267
	Engine No	4B12QR5032
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	03/08/2021/ 13:07	QUK	282 / Kevin Leong	13842		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	BRACKET,RADIATOR GRILLE,RH			1.00	17.00	23.00	13.09
M	BRACKET,RADIATOR GRILLE,LH			1.00	13.00	23.00	10.01
M	BRACKET,RADIATOR GRILLE,RH			1.00	17.00	23.00	13.09
M	BRACKET,RADIATOR GRILLE,LH			1.00	13.00	23.00	10.01
M	BRACKET,RADIATOR GRILLE			1.00	12.00	23.00	9.24
M	BRACKET,RADIATOR GRILLE			1.00	10.00	23.00	7.70
M	FENDER,FR RH			1.00	622.00	23.00	478.94
M	PANEL,HEADLAMP SUPPORT,UPR			1.00	230.00	23.00	177.10
M	PNL,HEADLAMP SUPT,UPR RH			1.00	0.00	23.00	
M	COVER,ENG ROOM UNDER,FR			1.00	349.00	23.00	268.73
M	GARNISH,FR BUMPER SIDE			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE			1.00	112.00	23.00	86.24
M	GARNISH,FR BUMPER SIDE			1.00	48.00	23.00	36.96
M	REINFORCEMENT,FR BUMPER			1.00	505.00	23.00	388.85
M	REINFORCEMENT,FR BMPR SIDE			1.00	22.00	23.00	16.94
M	REINF,FR BUMPER SIDE,RH			1.00	69.00	23.00	53.13
M	REINFORCEMENT,FR BUMPER			1.00	135.00	23.00	103.95
M	COVER,FR BUMPER			1.00	281.00	23.00	216.37
M	GRILLE ASSY,RADIATOR			1.00	572.00	23.00	440.44
M	COVER,FR BUMPER			1.00	25.00	23.00	19.25
M	WHEEL,SPARE TIRE DISC			1.00	1102.00	23.00	848.54

Confirm & accepted by

7% GST on	Nett 11651.35	11,651.35
		815.59
Total Payable		12,466.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.