

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS3/SGK21008162/Vvf3	
c/o SEDGWICK SINGAPORE PTE LTD		Date: 03/08/2021	
30 CECIL STREET, LEVEL 12			
PRUDENTIAL TOWER			
SINGAPORE 049712SINGAPORE 079120			
		Code: AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	FBR 9899X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KENNETH NEO	Assign Date	03/08/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/07/2021	Inspection Date	03/08/2021
Survey held at	10 Kaki Bukit Road 2 #01-06		
Repairer	BIKE IMAGE MOTOR TRADING		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			