




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SEDGWICK SINGAPORE PTE. LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712			Ref: CS3/SGK21008162/Vvf3e2 Date: 10/08/2021 Code: SGK	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	FBR 9899X	
Policy No.		Coverage (\$)	0.00	
Claim No.	6005788	Excess (\$)	0.00	
Assign From	KENNETH NEO	Assign Date	03/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400XA	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JH2NC5696KK000342	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80 R19	DUNLOP	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/60 R17	DUNLOP	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information				
Accident Date	28/07/2021	Inspect Date / Time	03/08/2021 (02:30 PM)	
Survey held at	10 Kaki Bukit Road 2 #01-06			
Repairer	BIKE IMAGE MOTOR TRADING			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/SGK21008162/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.