

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 1

#01-80 SINGAPORE 159723

TEL: 62715133 62717433 FAX: 62745715

Steve (CLKK)
3/8/21, 3:37pm

W/L AL
4 dyl

L/S

M AL dy

Pg1

ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 2.8.2021

Owner's Name : Tan Guo Quan

Vehicle No : SMS1333D

Vehicle Make & Model : Honda Shuttle Hybrid 1.5 A

Registration Date : 14 Jun 2018 (YOM 2018) COE Expiry Date 13 Jun 2028

Claim Type: Third Party Claim

Chassis No: GP71211221

DOA: 1.8.2021

No	Description	Unit	List (\$)
1	REAR TAIL GATE / DD	1	\$ 1193 / 1,284.12
2	REAR TAIL GATE HINGE X NN	2	\$ 120.00
3	REAR TAIL GATE LOCK / BT	1	\$ 225 / 316.60
4	REAR TAIL GATE LOCK X NN	1	\$ 65.00
5	REAR TAIL GATE LOGO X NN	1	\$ 390.70
6	REAR TAIL GATE CHROME PANEL X NN	1	\$ 65.00
7	REAR TAIL GATE "SHUTTLE" / MC	1	\$ 88-40 / 125.00
8	REAR TAIL GATE "HYBRID" / MC	1	\$ 972 / 1,197.18
9	REAR BUMPER / DD	1	\$ 140.00
10	REAR BUMPER SIDE RETAINER / BR	2	\$ 130.00
11	REAR BUMPER REFLECTOR X NN	2	\$ 190.00
12	REAR BUMPER REFLECTOR GARNISH X NN	1	\$ 759.16
13	REAR END PANEL ? X NN	1	\$ 165.60
14	REAR END PANEL GARNISH ? X NN	1	\$ 325.00
15	REAR REINFORCEMENT X NN	1	\$ 205.65
16	REAR ANTENNA SENSOR ? X NN	1	\$
			2683.40
			- 20%
			P- 2146.72
			N- 270
			L- 960
			3376.72
			L/S - 2701.37
			= 2700
		Total (A):	\$ 5,479.01
		Less 20%	\$ 1,369.75
		Total:	\$ 4,109.26

BLOCK 1009 RUKIT MIRAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133, 62717433 FAX: 62745715

ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 2.8.2021

Owner's Name : Tan Guo Quan

Vehicle No : SMS1333D

Vehicle Make & Model : Honda Shuttle Hybrid 1.5 A

Registration Date : 14 Jun 2018 (YOM 2018) COE Expiry Date 13 Jun 2028

Claim Type: Third Party Claim

Chassis No: GP71211221

DOA: 1.8.2021

No	Description	Unit	List (\$)
	Special Nett		
1	TAILGATE SEALANT / NKK	1	\$ 40 ✓ 80.00
2	REAR BUMPER CLIPS / NKK	SET	\$ 30 ✓ 40.00
3	REAR END PANEL GARNISH CLIPS ? X nn	6	\$ 70.00
4	REAR FENDER SHIELD CLIPS X nn	2 SET	\$ 70.00
5	REVERSE SENSOR / Should	SET	\$ 290 ✓ 280.00
		270	
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 400 800.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 400 1,000.00
3	Check Wiring System & Light	1	\$ 30 100.00
4	Anti Rust Treatment	1	\$ 30 120.00
5	To Remove/Replace/Refix Tailgate Windscreen To New Tail Gate	1	\$ 120.00
6	To Remove / Refix Rear Inner Compartment To Facilitate Repair	1	\$ 30 150.00
7	To Remove / Refix Rear Top Tailgate Spoiler	1	\$ 30 100.00
8	To Remove / Replace/ Refix Rear Reverse Camera & Reverse Sensor	1	\$ 30 180.00
9	To Remove / Refix Rear Tail Gate Attachment	1	\$ X 120.00
10	Computer Diagnostic	1	\$ X 350.00
		960	
	Customer to provide to Honda notify the Repairs of the following: - To display damaged parts during survey - To supply damaged parts to repairer - That party involved on a "Not at Fault" basis - Supplementary items must be surveyed and subject to final approval from Insurance Company		
		Total (B) :	\$ 3,540.00
		Grand Total:	\$ 7,649.26

Acknowledgments

5-2-02

Case: