

TP A16.

SDJ8810B. 2016 Oct.

Jasper.

Mercedes Benz E220D 1950cc.

WDD2130042A057800

Rear Bumper	Defend	1825	✓
Rear Bumper Clips	in	50(SN)	✓
Rear Bumper Side Holder	x 02 ^{RH} and	94 x 2 = 188	94
Rear Bumper Tow Cover	in	58	✓
Rear Bumper Lower Garnish	Defend	685	✓
Rear Bumper Lower Chrome Moulding	in	388	✓
Rear Bumper Exhaust Chrome Moulding	x 02 ^{new}	168 x 2 = 336	X
Rear Bumper Reinforcement	Dented	769.	✓
Rear Bumper Inner Frame	could	278	✓
Rear Bumper Exhaust Chrome Moulding Bracket	x 02	95 x 2 = 190	✓
Rear Bumper Lower Cover	in	245	✓
Rear Bumper Kick Sensor	in	322	✓
Reverse Sensor	x 04. ^{2 pieces} dented	265 x 4 = 1060	530
Rear End Panel	Repair	1350	✓
Rear End Panel Top Garnish	in	156	✓
Rear End Panel Sealant	in	60(SN)	✓

SJD8810B.

Bootlid Buckled
 Bootlid Lock
 Bootlid Weatherstripe.

Mercedes Logo.

Taillamp x 02

Taillamp Lower Bracket x 02.

Panel Beating
 Spray Painting.
 Wiring.

To remove cruise sensor. 1850

To perform diagnostic

To spray tuff coat.

To remove upholstery.

To remove rear camera.

To transfer bootlid fittings.

2293 ✓

283 X

261 X

85 ✓

775
 $775 \times 2 = 1550$

116.
 $116 \times 2 = 232$

S.N: 50

~~1200~~ 700

~~1200~~ 750

~~50~~ 30

~~150~~ 60

~~200~~ 120

~~150~~ 50

~~150~~ 60

100 X

~~150~~ 80

total: 9425.20

48: 73K
 ASDMys.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: