



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:ONG KIAN THENG DERICK			Ref: CC4/ASM21008170/Kgs3q2 Date: 18/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 5888P	Veh. Inspected	SMU 5893S	
Policy No.	GA461139	Coverage (\$)	0.00	
Claim No.	S1M03ESI	Excess (\$)	0.00	
Assign From		Assign Date	03/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WDC1569422J678294	Colour	RED	
Odometer	18576 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	CONTINENTAL	8 mm	
L/H Front Tyre	235/50 R18	CONTINENTAL	8 mm	
R/H Rear Tyre	235/50 R18	CONTINENTAL	8 mm	
L/H Rear Tyre	235/50 R18	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/07/2021	Inspection Date	12/08/2021	
Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	