



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CC3/CTI21008172/R1ea3q2 Date: 18/10/2021 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SML 4622L | Veh. Inspected | SHC 3782X | |
| Policy No. | DMHCSNW00004872100 | Coverage (\$) | 0.00 | |
| Claim No. | SNM21D204262/C02/TANCHC | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 02/08/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI IONIQ HEV FL 1.6 DCT | c.c | 1580 | |
| Engine No. | HIDDEN | Year of Reg. | 2019 | |
| Chassis No. | KMHC851CVLU188159 | Colour | BLUE | |
| Odometer | 265150 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm | |
| L/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 30/07/2021 | Inspection Date | 02/08/2021 | |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3782X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT DOOR OUTER HANDLE RH | TO REPAIR SEE LABOUR | 234.80 | - |
| 1 | FRONT DOOR PROTECTOR RH | SCRATCHED | 110.10 | 110.10 |
| 1 | REAR DOOR PROTECTOR RH | SCRATCHED | 125.30 | 125.30 |
| 1 | REAR WHEEL COVER RH | SCRATCHED | 346.40 | 346.40 |
| | LESS 20% DISCOUNT | | -163.32 | -116.36 |
| | | | 653.28 | 465.44 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRONT DOOR COMFORT LOGO STICKER (SN) | NOT NECESSARY | 75.00 | - |
| 1 | REAR DOOR COMFORT APP STICKER (SN) | NECESSARY | 80.00 | 80.00 |
| | | | 155.00 | 80.00 |
| <u>LABOUR</u> | | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE RH . | | 600.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 900.00 | 500.00 |
| | REMOVE/REFIX UPHOLSTERY . | NOT NECESSARY | 90.00 | - |
| | CHECK WIRING . | NOT NECESSARY | 60.00 | - |
| | | | 1,650.00 | 850.00 |
| GRAND TOTAL | | | 2,458.28 | 1,395.44 |
| RECOMMENDED COST OF REPAIRS | | | | 1,395.44 |

Report Ref No. CC3/CTI21008172/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3782X

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3782X

RE-INSPECTION

