



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

TP III Asher.

MR053ZEE106113401

Vehicle No. SJK4117U TOYOTA ALTIS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	F ARTS (LIST ITEMS)			
1	REAR BOOTLID <i>Buckled</i>		839.40	✓
1	REAR BOOTLID LOGO		87.60	✓
1	REAR BOOTLID "COROLLA" EMBLEM		81.00	✓
1	REAR BOOTLID "ALTIS" EMBLEM		68.00	✓
1	REAR BOOTLID LOCK SWITCH <i>new</i>		195.00	+
1	REAR BOOTLID INNER LOCK <i>Dented</i>		284.50	✓
1	REAR BOOTLID INNER TRIM <i>new</i>		265.40	x
1	REAR BOOTLID W/STRIP <i>lt</i>		232.80	✓
2	REAR BOOTLID LAMP LH & RH @\$360.90 <i>new</i>		721.80	x
2	REAR NUMBER PLATE LAMP LH & RH @\$105.50 <i>new</i>		211.00	x
1	REAR BUMPER <i>rebound</i>		676.70	576
1	PEAR BUMPER RINFORCEMENT BEAM <i>new</i>		443.70	x
2	REAR BJMPER SIDE BRACKET LH & RH @\$68.50 <i>Dented</i>		137.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$119.20 <i>new</i>		238.40	90
2	REAR BUMPER REFLECTOR LH & RH @\$137.80 <i>new</i>		275.60	x
1	REAR BUMPER SPONGE <i>crushed</i>		169.00	✓
1	REAR END PANEL <i>Dented</i>		615.30	✓
1	REAR END PANEL TOP GARNISH <i>Dented</i>		278.50	✓
1	REAR SPARE TYRE TOP BOARD	3734.10	475.80	x
1	REAR SPARE TYRE PANEL	2800.57	797.00	x
1	REAR SMART KEYLESS ANTENNA		195.20	x
1	REAR TAILLAMP LH <i>lt</i>		428.60	365
		less	25%	25%
			7717.30	
			1929.33	
			5787.98	
	SPECIAL NETT ITEMS			
1 SET	REVERSE SENSOR <i>Dented</i>		350.00	200
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	30
1 SET	REAR BOOTLID LAMP CLIPS <i>new</i>		100.00	+
1	REAR END PANEL SEALANT <i>new</i>		80.00	60
1	REAR SPARE TYRE PANEL SEALANT <i>new</i>		80.00	x
	Total Parts		6477.98	

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SJK4117U TOYOTA ALTIS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	800
3	To remove, refix wiring system at accident damage areas and check for proper function	150.00	30
4	To transfer rear boot mechanism	120.00	80
5	To perform anti-rust treatment on affected areas	180.00	60
6	To conduct water seepage test	120.00	X
7	To remove and refix rear windscreen	120.00	X
Labour Total :		3890.00	
TOTAL (PARTS & LABOUR):		10367.98	

Supplementary: 756.60

Total: 5617.57

L/S: A.S.K.

06 Dm/s.

(A.S.K.)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJK 4117U. Supplementary.

Taillamp RH. Lit

365

~~428.60~~ -

Rear Bumper Impact Bracket x 02 Dented RT. Q x 2 = 195.80. ✓

Boothlid LX 1.6 Emblem. ✓

84 ✓

728.80

546.60

To remove and refix upholstery

~~150.~~ 80.

To remove reverse sensor

~~100.~~ 50

To remove and refix boothlid Spoiler

~~100.~~ 80.

210

Supplementary: 736.60.