

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008177/GQCQ2**Date:** 18/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00086362002
<b>Claimant Vehicle No :</b>	SLR9665K	<b>Insured Vehicle No :</b>	GQ7571A
Date of Loss:	29/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D204235/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLR9665K</b>	Engine No:	LEB5255373
Make & Model:	HONDA GRACE, 1.5 (A)	Chassis No:	GM41105359
Reg. Date:	31/08/2017 (Man. Year: 2016)	Odometer:	241375 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,167.20	1,262.16	2,905.04	69.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	940.00	860.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,967.20</b>	<b>2,202.16</b>	<b>3,765.04</b>	<b>63.10</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,750.00</b>		
<b>(\$\$)</b>	5,967.20	1,750.00	4,217.20	70.67
<b>+ GST 7.00/7.00% (\$\$)</b>	417.70	122.50	295.20	70.67
<b>Nett Amount (\$\$)</b>	<b>6,384.90</b>	<b>1,872.50</b>	<b>4,512.40</b>	<b>70.67</b>

**INSPECTION**

Date of Assignment:	03/08/2021	
Date Inspected:	04/08/2021	Inspected At: 60 Jalan Lam Huat, #04-39/40 Carros Centre
Estimated Period of Repair:	4.0 days	Repairer: Lion City Rental (jalan Lam Huat ) (HQ)

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	143	HONDA GRACE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9665K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	1,590.00 FL	*725.40 FL
2	1		*REAR BOOT LOCK	Not Necessary	160.00 FL	*- FL
3	1		*REAR BOOT HYBRID EMBLEM	Necessary	78.00 FL	*78.00 FL
4	1		*REAR BOOT HONDA LOGO	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BOOT GRACE EMBLEM	Necessary	60.00 FL	*60.00 FL
6	1		*REAR END PANEL	Repair	400.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	480.00 FL	*- FL
8	1		*REAR BUMPER	Repair	980.00 FL	*- FL
9	1		*REAR BUMPER LH RETAINER	Not Necessary	42.00 FL	*- FL
10	1		*REAR BUMPER RH RETAINER	Not Necessary	42.00 FL	*- FL
11	1		*REAR BUMPER LH BRACKET	Not Necessary	36.00 FL	*- FL
12	1		*REAR BUMPER RH BRACKET	Not Necessary	36.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*SET REVERSE SENSOR	Not Necessary	260.00 FS	*- FS
15	1		*REAR SPOILER	Cracked	480.00 FL	*461.00 FL
16	1		*REAR BOOT CENTER GARNISH CHROME	Deformed	350.00 FL	*165.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,124.00	1,570.20
- List Item Discount on L Items 20.00/20.00% (S\$)	956.80	308.04
Total Parts (S\$)	4,167.20	1,262.16

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING REAR BOOT ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY REAR TAILGATE ,REAR END PANEL ,SPARE TYRE PANEL ,REAR BUMPER	New	900.00	440.00
<b>Gross Labour Cost (S\$)</b>			<b>1,800.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >