

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 05 Aug 2021

**Preliminary Advice**

Insured Vehicle No	: GQ7571A		
TP Vehicle No	: SLR9665K	Accident Date	: 29/07/2021
Make	: HONDA GRACE	Assignment Date	: 03/08/2021
Date of Inspection	: 04/08/2021	Est. Duration of Repair	: 4
Inspection At	: LION CITY RENTAL (JALAN LAM HUAT ) (HQ) 60 JALAN LAM HUAT, 04-35/36 CARROS CENTRE SINGAPORE 737869		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,303.20
Revised Amount	:S\$	2,442.40
Check Items (Estimated)	:S\$	384.00
Total	:S\$	2,826.40

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.