

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd

Date 2/8/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLR9665K

CHASSIS NO :GM41105359

MAKE / MODEL : Honda Grace 1.5 Hybrid DX CVT

DATE OF ACCIDENT: 29/07/2021

YOUR INSURED VEHICLE NUMBER : GQ7571A

MILEAGE: 241375 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT</u>	<u>LIST PRICE</u>
1	Rear boot / <i>Paint</i>	1PC	\$ 1,590.00	\$ 1,590.00
2	Rear boot lock X <i>NN</i>	1PC	\$ 160.00	\$ 160.00
3	Rear boot Hybrid emblem / <i>MC</i>	1PC	\$ 78.00	\$ 78.00
4	Rear boot Honda logo / <i>MC</i>	1PC	\$ 50.00	\$ 50.00
5	Rear boot GRACE emblem / <i>MC</i>	1PC	\$ 60.00	\$ 60.00
6	Rear end panel X <i>Repair</i>	1PC	\$ 400.00	\$ 400.00
7	Rear bumper reinforcement ?	1PC	\$ 480.00	\$ 480.00
8	Rear bumper X <i>Repair</i>	1PC	\$ 980.00	\$ 980.00
9	Rear bumper LH retainer X <i>NN</i>	1PC	\$ 42.00	\$ 42.00
10	Rear bumper RH retainer X <i>NN</i>	1PC	\$ 42.00	\$ 42.00
11	Rear bumper LH bracket X	1PC	\$ 36.00	\$ 36.00
12	Rear bumper RH bracket X	1PC	\$ 36.00	\$ 36.00
LIST TOTAL S\$:				\$ 3,954.00
20.00% DISCOUNT S\$:				\$ 790.80
				\$ 3,163.20

SPECIAL NETT

1	Rear bumper clips / <i>MC</i>	1 SET	\$ 80.00
2	Reverse sensor X <i>NN</i>	1 SET	\$ 260.00
Special Nett Total S\$:			\$ 340.00

LABOUR CHARGES

- 1 To labour charge for removing rear boot, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts. 250 \$ 900.00 500
- 2 To respray rear tailgate, rear end panel, spare tyre panel, rear bumper 220 \$ 900.00 440

LABOUR TOTAL S\$: \$ 1,800.00
TOTAL S\$: \$ 5,303.20
7% GST \$ 371.22
GRAND TOTAL S\$: \$ 5,674.42

4 Days

Unpenn Repair

After my air photos

Gene Q: a/f

94/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: