

TPSMRT.
Hui Zhen.

SLW402SP. 2009 Sept.

Toyota Altis. 1598cc

MROS3, ZEE106152105

Rear Bumper	Distorted	557.60.	✓
Rear Bumper Clips	me	30(SN)	✓
Rear Bumper Side Holder x 02	me	$57 \times 2 = 114$	✓
Rear Bumper Sponge	Amld	138.20	✓
Rear Bumper Impact Bracket x 02	LH Dented	85.60	
		$85.6 \times 2 = 171.20$	
Rear Bumper Reflector x 02	ALPm	$35.7 \times 2 = 71.40$	+
Reverse Sensor	Dmgd	280(SN) 2nd(SN)	
Rear End Panel	Dented	532	✓
Rear End Panel Top Garnish	del	164.20	✓
Rear End Panel Top Garnish Clips	me	10(SN)	✓
Taillamp x 02	Amld	362	
		$362 \times 2 = 724$	✓
Bootlid	Regis	822.30	+
Bootlid Lock	MP me	159.40	+

SLW 402SP

Bootlid Weathershipe. ~~165.20~~ ✓

Toyota Logo.

48 ✓

1.6 Emblem.

47 ✓

Corolla Wording

46 ✓

Altis Wording

52 ✓

Spare Tyre Panel Top Board.

torn

285.40. ✓

2959.20 SIN: 240

2219.40

Panel Beating

~~1200~~ 600

Spray Painting.

~~1000~~ 600

Wiring.

1440

~~500~~ 300

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~150~~ 80

To spray tuff coat.

~~150~~ 80

To remove rear camera.

100X.

total: 3899.40

1/5: 3.1K.
05 Days

TOTAL \$6143.43

(3100)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: