

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	F	Ref:	CS/CTI21008181/T1qc		
	3 ANSON ROAD # SPRINGLEAF TOV	Г	Date:	03/08/2021		
			C	Code:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMP 7230T	Veh. Inspected		SLX 7886X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D204242/C02/SMP7230 T/LEEPG	Excess (\$)		0.00	
	Assign From	CECILIA LEE PENG GEOK	Assign Date		03/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes	rakes Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	29/07/2021	Inspection Date		03/08/2021	
	Survey held at	56 LOYANG WAY, #04-04 LOYA	ANG ENTERPRISE BUILDING			
	Repairer	airer AP AUTOMOTIVE SERVICES PTE LTD				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					