



# LKK Auto Consultant's henceforth the Repairer of the following.

Neg no: 2016058782  
 Address: 809 JALAN LAM HUA, CARROS CENTRE #05-68 5737869  
 Tel: 98888888

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## Estimation

Date: 4/8/2021  
 Vehicle: SMN3363E  
 Make / Model: HONDA SHUTTLE  
 Chassis: GK8-2101980

Acknowledged by Repairer  
 Signature:  
 Date:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / BR	1	\$ 1,250.00	\$ 1,250.00
2	FRONT BUMPER SIDE RETAINER LH / BR	1	\$ 18.70	\$ 18.70
3	FRONT BUMPER FOG LAMP COVER LH X	1	\$ 165.00	\$ 165.00
4	HEADLAMP LH X	1	\$ 950.00	\$ 950.00
5	HEADLAMP LOWER BRACKET LH X	1	\$ 78.00	\$ 78.00
6	FRONT FENDER LH / BR	1	\$ 411.90	\$ 411.90
7	FRONT FENDER INNER SHIELD LH / BR	1	\$ 145.00	\$ 145.00
8	FRONT FENDER INNER EMBLEM LH / BR	1	\$ 42.00	\$ 42.00
9	FRONT SHOCK ABSORBER LH X	1	\$ 456.00	\$ 456.00
10	FRONT KNUCKLE ARM LH X	1	\$ 398.00	\$ 398.00
11	FRONT KNUCKLE ARM BEARING LH / BR	1	\$ 215.00	\$ 215.00
12	FRONT LOWER ARM LH / BR	1	\$ 548.00	\$ 548.00
				\$ 4,677.60
				Less 20%
				\$ 935.52
				Total
				\$ 3,742.08
S/Nett items:				
1	FRONT FENDER INNER SHIELD CLIPS SET / BR	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP SET / BR	1	\$ 80.00	\$ 80.00
3	FRONT SPORTS RIM LH / Cust	1	\$ 600.00	\$ 600.00
				\$ 760.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND RENEW FRONT UNDERCARRIAGE	1	\$ 400.00	\$ 400.00
3	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00
4	TO RESPRAY UNDERCOATING	1	\$ 300.00	\$ 300.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,595.00
CDAYS - Impor repair After repair photos - 03/8/21			Parts Replacement Amount \$ 4,502.08 Total Amount for Labour \$ 2,595.00 <b>Total Amount \$ 7,097.08</b>	250 20 150 60 40 400 300