

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21008187/KRA3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0004034_01
Claimant Vehicle No :	SKW6897M	Insured Vehicle No :	GBD2475E
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0003275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6897M		
Make & Model:	MERCEDES-BENZ 260E, 2.6 (A)	Engine No:	10394022052252
Reg. Date:	06/10/1988 (Man. Year: 2020)	Chassis No:	WDB1240262A832327
Colour:	Metallic Silver	Odometer:	193315 km
Engine Capacity:	2599 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,787.90	5,045.40	742.50	12.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,420.00	140.00	8.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,347.90	6,465.40	882.50	12.01
Approved Total (Overridden) (S\$)		5,150.00		

(S\$)	7,347.90	5,150.00	2,197.90	29.91
+ GST 7.00/7.00% (S\$)	514.35	360.50	153.85	29.91
Nett Amount (S\$)	7,862.25	5,510.50	2,351.75	29.91
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,352.50		

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 03/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	143	MERCEDES-BENZ 260E 2.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6897M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,965.00 FL	*1,780.00 FL
2	1		*BOOT LID STAR	Necessary	55.00 FL	*55.00 FL
3	1		*BOOT LID OUTER CHROME	Serviceable	448.00 FL	*- FL
4	1		*REAR END PANEL	Bent	540.00 FL	*540.00 FL
5	1		*REAR BUMPER FASCIA	Buckled	1,620.00 FL	*1,620.00 FL
6	1		*REAR BUMPER TOP CHROME	Dented	467.00 FL	*467.00 FL
7	2		*REAR BUMPER SIDE CHROME	Necessary	792.00 FL	*660.00 FL
8	1		*REAR BUMPER CENTRE PAD	Cracked	484.00 FL	*484.00 FL
9	1		*REAR BUMPER SPONGE	Serviceable	60.00 FL	*- FL
					Sub Total (\$\$)	6,431.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	643.10
					Total Parts (\$\$)	5,787.90
						5,045.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY UNDERSEALING	New	60.00	60.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	700.00	660.00
3	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	800.00	700.00
Gross Labour Cost (\$\$)			1,560.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >