

ASS. REC. BY:

REF:

III / 21008187/K

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

03/29

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PKW-68974 Regn: 10, 88

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer 260 E c.c. 2599

Colour:

M-Silver A/C: Insured / Std / NI / NA

Sp. Reading

193315 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDB1240262A 832327

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/458R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

S mm

R/Bal.

S mm

L/Bal.

S mm

L/Bal.

S mm

D.O.A.

26/7/21

D.O.I.

3/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/8 11PM 851506 Condur

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06427

Vehicle Insured : GBD2475E
Accident Date : 26-Jul-2021

Date : 02-Aug-2021

Our Ref : 021111 (III) / CHAN

PAGE : 1

TAN BOON KWONG
BLK 1 TANJONG PAGAR PLAZA
#10-53
Singapore 082001

Not Authored
LI Rep @ 5150/hr
Meaning After Paim
3 days

ESTIMATED COST OF REPAIR FOR M/BENZ 260E SKW6897M

=====

1 pc	Boot lid	1780			1,965.00	✓
1 pc	Boot lid star				55.00	✓
1 pc	Boot lid outer chrome				448.00	X
1 pc	Rear end panel				540.00	✓
1 pc	Rear bumper fascia				1,620.00	✓
1 pc	Rear bumper top chrome				467.00	✓
2 pcs	Rear bumper side chrome	0330	@ S\$396.00		792.00	✓
1 pc	Rear bumper centre pad				484.00	✓
1 pc	Rear bumper sponge				60.00	X

6,431.00

Less 10% : 643.10

5,787.90

To apply undersealing

60.00 ✓

To putty and spray replaced parts

700.00 6601

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 7001

Total : S\$ 7,347.90

=====

Singapore Dollars Seven Thousand Three Hundred
and Forty Seven and Cents Ninety Only

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: