

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0625/2021/KS
DATE : 2-Aug-21
WIP : 37916

Xiao Chan .

\$ 32512.68.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 03/08/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ONG BOON CHONG
ADDRESS : 21 TERASSE LANE
 #05-10
 SINGAPORE 544774
TELEPHONE : HP +65 97618766
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210029521
VEHICLE NO : SMH 9997 T
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFSI
MODEL YEAR : 24/3/2021
ENGINE NO : DEM 031017
CHASSIS NO : WAUZZZF5XMA033251
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Aug-21
PLACE OF ACCIDENT : POH HUAT ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 9997 T.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$ 3,200.00	? ✓
4	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	? ✓
5	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 280	✓
6	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	X
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS SILL PANEL TRIM AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS A-PILLAR AND RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,800.00 2000	3500 (Not inclusive of A pillar)
TOTAL LABOUR CHARGES		: \$ 15,480.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 9997 T.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	✓ TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, ✓ BONNET, RHS A-PILLAR, RHS SILL PANEL, ✓ RHS SILL PANEL TRIM, DOOR ENTRANCE, RHS FRONT DOOR, HINGES, ✓ RHS WING MIRROR COVER AND RHS REAR DOOR. ✓	S 8,600.00	2350 3175 4 x 550 = 2200 Mirror = 150 <u>2350</u>
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N S 280.00	X
10	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N S 2,400.00	? ✓
11	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N S 800.00	? ✓
12	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N S 2,400.00	? ✓
13	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N S 520.00	✓ ✓
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 384.00	✓ ✓
TOTAL LABOUR CHARGES		: S <u>30,864.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 9997 T

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER	1	S	2,342.00	+	
2	FRONT BUMPER SECURING STRIP	2	S	71.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	S	262.00	+	
4	FRONT BUMPER AIR GUIDE - RH	1	S	63.00	+	
5	FRONT BUMPER AIR GUIDE GRILLE - RH	1	S	135.00	+	
6	FRONT BUMPER TRIM - RH	1	S	48.00	+	
7	FRONT BUMPER GUIDE SECTION - RH	1	S	36.00	+	
8	FRONT FENDER - RH	1	S	1,060.00	✓	848
9	FRONT FENDER ATTACHMENT PARTS - RH	1	S	53.00	?	X
10	FRONT FENDER CLOSING ELEMENT - RH	1	S	74.00	?	X
11	FRONT FENDER BRACKET - RH	1	S	35.00	?	X
12	FRONT FENDER BRACE - RH	1	S	118.00	?	X
13	FRONT FENDER CLOSING ELEMENT - RH	1	S	33.00	?	X
14	FRONT FENDER CHROME TRIM - RH	1	S	164.00	✓	130.80
15	FRONT WHEEL HOUSING LINER - RH	1	S	275.00	✓	219.60
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1	S	169.00	?	X
17	FRONT FENDER FLEDGE COVER - RH LONG	1	S	36.00	?	X
18	FRONT FENDER FLEDGE COVER - RH SHORT	1	S	16.00	?	X
19	LED HEADLIGHT - RH	1	S	7,685.00	X	
20	BONNET	1	S	3,312.00	X	
TOTAL SPARE PARTS			:	\$	15,987.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 9997 T

				DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	BONNET ATTACHMENT PARTS	1	\$ 123.00			
22	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00			
23	BONNET IMPACT PROTECTION - LH / RH	2	\$ 56.00			
24	SECTIONAL PANEL - A/B PILLAR	1	\$ 2,179.00	1743.20		
25	CHASSIS DATA TAG	1	\$ 462.00	369.60		
26	SILL TRIM STRIP - RH	1	\$ 120.00	96.00		
27	FRONT DOOR - RH	1	\$ 3,884.00	3107.20		
28	FRONT DOOR OUTER SEAL - RH	1	\$ 222.00	177.60		
29	BONDING AGENT	1	\$ 49.00	X		
30	CLEANING SOLUTION	1	\$ 68.00	X		
31	APPLICATOR	1	\$ 8.00	X		
32	FRONT DOOR CATCH - RH	1	\$ 120.00	X		
33	FRONT DOOR HINGE HALF- UPPER PART, RH UPPER	1	\$ 44.00	34.48		
34	FRONT DOOR HINGE HALF- LOWER PART, RH UPPER	1	\$ 45.00	35.52		
35	FRONT DOOR HINGE HALF- UPPER PART, RH LOWER	1	\$ 47.00	37.60		
36	FRONT DOOR HINGE HALF- LOWER PART, RH LOWER	1	\$ 45.00	35.84		
37	FRONT DOOR SEAL, INNER - RH	1	\$ 589.00			
38	FRONT WING MIRROR MOUNTING - RH	1	\$ 1,826.00	1460.80		
39	FRONT WING MIRROR CAP - RH	1	\$ 289.00	231.20		
40	FRONT WING MIRROR GLASS - RH	1	\$ 1,667.00	X		
TOTAL SPARE PARTS		:	\$ 11,871.00			



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 9997 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	DATA PLATE FOR TYRE PRESSURE <i>see</i>	1	S	37.00	29.04
42	FRONT DOOR CHROME TRIM - RH <i>see</i>	1	S	164.00	✓ 130.80
43	ROOF MOLDING, CHROME - RH <i>see</i>	1	S	629.00	+
44	WATER DEFLECTOR STRIP - RH <i>see</i>	1	S	67.00	+
45	FRONT WINDOW SLOT SEAL CHROME TRIM - RH <i>see</i>	1	S	399.00	+
46	FRONT WINDOW CORNER TRIM - RH <i>see</i>	1	S	46.00	✓ 36.24
47	FRONT DOOR WINDOW - RH <i>see</i>	1	S	290.00	+
48	FRONT WINDOW APERTURE SEAL - RH INNER <i>see</i>	1	S	407.00	+
49	FRONT WINDOW REGULATOR - RH <i>Noe Nec</i>	1	S	368.00	?
50	FRONT WINDOW REGULATOR MOTOR - RH <i>see</i>	1	S	331.00	+
51	FRONT DOOR WIRING SET - RH <i>Noe Nec</i>	1	S	577.00	?
52	SIDE MEMBER TRIM - RH <i>Del'd</i>	1	S	869.00	✓ 695.20
53	SIDE MEMBER TRIM ATTACHMENT PARTS - RH <i>see</i>	1	S	130.00	✓ 104.00
54	SIDE MEMBER TRIM ADHESIVE TAPE - RH <i>see</i>	1	S	212.00	✓ 169.60
55	STONE CHIP GUARD - RH <i>Del'd</i>	1	S	51.00	✓ 40.32
56	SILL PANEL TRIM BRACKET - RH <i>Cracked</i>	1	S	24.00	✓ 18.80 ✓
57	UNDERBODY TRIM - RH <i>see</i>	1	S	323.00	+
58	UNDERBODY TRIM - RH FRONT <i>see</i>	1	S	43.00	+
59	FRONT SUBFRAME <i>Noe nec</i>	1	S	1,891.00	?
60	FRONT LOWER ARM - RH <i>Bent</i>	1	S	539.00	?
TOTAL SPARE PARTS			:	\$	7,397.00

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 9997 T

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
61	FRONT SUSPENSION GUIDE - RH <i>Bent</i>	1	\$ 9,743.00	? 754.40	✓	
62	FRONT UPPER ARM - RH FRONT <i>NN</i>	1	\$ 512.00	? X		
63	FRONT UPPER ARM - RH REAR <i>NN</i>	1	\$ 512.00	? X		
64	FRONT WHEEL BEARING HOUSING - RH <i>Damaged</i>	1	\$ 967.00	? 774	✓	
65	FRONT LOWER ARM BALLJOINT - RH <i>Bent</i>	1	\$ 193.00	? 154.40	✓	
66	FRONT WHEEL HUB - RH <i>Damaged</i>	1	\$ 479.00	? 383.20	✓	
67	FRONT WHEEL BEARING - RH <i>Damaged</i>	1	\$ 246.00	? 196.80	✓	
68	FRONT SUSPENSION FORK - RH <i>KEP</i>	1	\$ 264.00	? X		
69	FRONT COUPLING ROD - RH <i>NCC</i>	1	\$ 127.00	? X		
70	FRONT ANTI ROLL BAR	1	\$ 433.00	? X		
71	FRONT DRIVESHAFT - RH <i>KEP</i>	1	\$ 2,650.00	X		
72	FRONT SHOCK ABSORBER - RH <i>KEP</i>	1	\$ 310.00	? X		
73	FRONT TIE ROD - RH <i>Bent</i>	1	\$ 99.00	? 78.88	✓	
74	FRONT TIE ROD END - RH <i>Bent</i>	1	\$ 197.00	? 157.20	✓	
75	ARCYLIC SEALANT <i>KEP</i>	S/N	\$ 180.00	? ✓		
76	CAVITY WAX <i>KEP</i>	S/N	\$ 140.00	? ✓		
77	STONE CHIP <i>KEP</i>	S/N	\$ 180.00	? ✓		
78	METAL FILLER POWDER <i>KEP</i>	S/N	\$ 280.00	? ✓		
79	FRONT RHS RIM <i>KEP</i>		PRICE TBA	✓		
80	FRONT RHS TYRE <i>del</i>		\$ 430.00	✓		
81	SUNDRIES <i>NCC</i>		\$ 500.00	? 162.56	✓	
TOTAL SPARE PARTS			\$ 53,697.00			
TOTAL LABOUR CHARGES			\$ 30,864.00			
GRAND TOTAL			\$ 84,561.00			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adnan Lj*
SURVEYED DATE : *03/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 08 Days 14 Days.*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: