Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Cecilia Lee 13 Sep 2021 Date:

Preliminary Advice

Insured Vehicle No : SML5783Z

TP Vehicle No : YQ3891P Accident Date : 27/07/2021 Make : ISUZU NJR85AUE6W Assignment Date : 05/08/2021

Date of Inspection : 05/08/2021 Est. Duration of Repair : 5

Inspection At : RICO 60 AUTO SERVICES PTE LTD (HQ)

8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,851.01
Revised Amount	:S\$	7,410.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,410.83
Lump Sum Repair	:S\$	5,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised) stated are subject to consistency (x)check, part prices and labour cost.