



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%15	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: China Taiping Insurance
Vehicle No : YQ 3891 P
Make & Model : ISUZU NJR88
DATE: 28/7/2021

JAA NJR88EM7100011

LKK.

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,514.00	\$ 1,514.00
2	TAIL GATE STICKER(ISUZU) <i>new</i>	1	\$ 102.00	\$ 102.00
3	TAIL GATE SIDE HANDLE <i>3 new</i>	2	\$ 179.00	\$ 358.00
4	TAIL GATE SIDE LOCK <i>RH Dented</i>	2	\$ 215.00	\$ 430.00
5	TAIL GATE SIDE LOCK BRACKET <i>RH Bent</i>	2	\$ 276.30	\$ 552.60
6	TAIL GATE LOWER SIDE RAILING <i>new Bent RH</i>	2	\$ 246.90	\$ 493.80
7	TAIL GATE LOWER SIDE RAILING MOUNTING <i>new Bent RH</i>	2	\$ 35.00	\$ 70.00
8	TAIL GATE HINGE <i>new</i>	3	\$ 124.10	\$ 372.30
9	END PANEL <i>Dented</i>	1	\$ 564.20	\$ 564.20
10	END PANEL REFELCTOR <i>new</i>	2	\$ 100.00	\$ 200.00
11	TAIL LAMP <i>RH cracked</i>	2	\$ 549.00	\$ 1,098.00
12	REAR CAR PLATE BRACKET <i>Bent</i>	1	\$ 186.00	\$ 186.00
13	REAR CAR PLATE LAMP <i>new</i>	1	\$ 60.00	\$ 60.00
14	REAR CAR PLATE LAMP COVER <i>cracked</i>	1	\$ 122.10	\$ 122.10
15	REAR TOW HOOD <i>new</i>	1	\$ 211.00	\$ 211.00
16	SPARE TYRE HOLDER SOPPORT MEMBER <i>new</i>	1	\$ 658.00	\$ 658.00
17	SPARE TYRE HOLDER <i>Dented</i>	1	\$ 350.00	\$ 350.00
18	REAR EXHAUST PIPE <i>Bent</i>	1	\$ 467.00	\$ 467.00
19	REAR EXHAUST PIPE CENTER <i>new</i>	1	\$ 998.00	\$ 998.00
20	REAR EXHAUST TOP MOULDING <i>new</i>	1	\$ 30.00	\$ 30.00
21	REAR EXHAUST TOP MOULDING BRACKET <i>new</i>	1	\$ 67.30	\$ 67.30
22	SIDE GATE RH <i>Repair</i>	1	\$ 1,898.60	\$ 1,898.60
23	SIDE GATE HINGE RH <i>3 new</i>	6	\$ 90.00	\$ 540.00
24	SIDE GATE BOTTOM PANEL RH	1	\$ 752.40	\$ 752.40

1185

215

276.30

286.80

35

265

549

			Subtotal :	\$ 12,095.30
			Less 15%	\$ 1,814.30
			Parts Total :	\$ 10,281.01

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	TAIL GATE ALUMINIUM PLATE <i>Revised</i>	1	\$ 1,200.00	\$ 1,200.00
2	TAIL GATE ALUMINIUM PLATE RIVET <i>new</i>	1	\$ 120.00	\$ 120.00
3	TAIL GATE STICKER(60km/h) <i>3 new</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE STICKER(13PAX)	1	\$ 40.00	\$ 40.00
5	SIDE GATE ALUMINIUM PLATE <i>2 new</i>	2	\$ 1,000.00	\$ 2,000.00
6	SIDE GATE ALUMINIUM PLATE RIVET <i>new</i>	1	\$ 100.00	\$ 100.00
7	SIDE GATE ALUMINIUM RAILING SET <i>new</i>	1	\$ 800.00	\$ 800.00
8	FLOOR PANEL ALUMINIUM PLATE <i>2 new</i>	1	\$ 1,600.00	\$ 1,600.00
9	FLOOR PANEL ALUMINIUM PLATE RIVET <i>new</i>	1	\$ 100.00	\$ 100.00
10	REAR WOODEN FLOOR PANEL <i>new</i>	1	\$ 1,200.00	\$ 1,200.00
11	REAR WOODEN CROSSMEMBER <i>new</i>	1	\$ 400.00	\$ 400.00
12	REAR BUMPER <i>Best</i>	1	\$ 1,200.00	\$ 1,200.00
13	REAR BUMPER BRACKET <i>Best</i>	2	\$ 400.00	\$ 800.00
14	REAR BUMPER REFLECTION STICKER <i>new</i>	1	\$ 100.00	\$ 100.00
15	REAR CAR PLATE <i>Best</i>	1	\$ 60.00	\$ 60.00
16	END PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
17	FLOOR PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
18	REAR STEP PANEL <i>new</i>	1	\$ 400.00	\$ 400.00
19	SPARE TYRE <i>new</i> <i>2210</i>	2	\$ 300.00	\$ 600.00
SPECIAL NETT				\$ 10,920.00

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00
TO PERFORM LIGHTING & WIRING CHECK	\$ 100.00
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00
REMOVE AND INSTALL REAR EXHAUST	\$ 300.00
REMOVE AND INSTALL TAIL GATE ,SIDE GATE	\$ 1,000.00
REMOVE AND RESEAL GATE RIVET SET	\$ 300.00
REMOVE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 150.00
LABOUR TOTAL	\$ 5,650.00

	Total Parts Cost	\$ 21,201.01
	Total Labour Cost	\$ 5,650.00
	Total Repair Cost	\$ 26,851.01

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Adrian Ly
L/s 05/08/21.

05 Days

total: 7410.82.

L/s: 5.9K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: